

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-33541
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Warn State A/C 2 DHC No. 2083
8. Well No. 26
9. Pool name or Wildcat Vacuum; Wolfcamp, Up Penn, Atoka
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3967' KB 3982'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Marathon Oil Company
3. Address of Operator P.O. Box 2490 Hobbs, NM 88240	4. Well Location Unit Letter E : 2180 Feet From The North Line and 400 Feet From The West Line Section 6 Township 18-S Range 35-E NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL 3967' KB 3982'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **Install rod pump. Plug back Atoka** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/30 RU pulling unit. NU BOP. POOH w/tbg. cable & sub pump. RIH w/RBP & pkr. Swab various intervals. Rel RBP at 9730, pkr at 9470', POOH.

6/3 RIH w/CIBP, set at 11,121'. Dump 2 sxs cmt. RIH w/2nd CIBP, set at 11,030'. Dump 2 sxs cmt. RIH w/3rd CIBP, set at 10,450'. No cmt dumped. RIH w/pkr, set at 9664'. Mix & pump 20 gals chemical. Swab.

6/7 RIH, rel pkr, POOH. RIH w/2 7/8" prod tbg.

6/8 ND BOP. NU wellhead. RIH w/pump & rods. Load & test, OK. RD pulling unit.

SN at 10,340'
Btm of tbg 10,375'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 7/12/00
TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: _____