

SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all well-stems, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
DELAWARE	5900	7544	OIL & GAS SANDS	T/SALT B/SALT YATES QUEEN DELAWARE BONE SPRINGS	1650 2805 3470 4190 5900 7544	

38.

GEOLOGIC MARKERS

