

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals & Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P. O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P. O. Box 2088  
Santa Fe, NM 87504-2088

WELL API NO. 30-025-33773
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1 Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
2. Name of Operator The Wiser Oil Company	8. Well No. 280
3. Address of Operator P.O. Box 2568 Hobbs, New Mexico 88241	9. Pool name or Wildcat Maljamar Grayburg San Andres
4. Well Location Unit Letter <u>M</u> : <u>932</u> Feet From The <u>South</u> Line and <u>330</u> Feet From The <u>West</u> Line Section <u>28</u> Township <u>17S</u> Range <u>33E</u> NMPM <u>Lea</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4088'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>Perforate, Acidize &amp; Frac</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

03/24/97 RIH w/2-7/8" tbg. & tagged @ 4390'. Drld. f/4390'-4467'. Circ. hole clean.

03/25/97 Drld. cmt. f/4467'-4569'. Circ. clean on top of RBP. POH w/tbg. & DC's. RIH w/retrieving tool on 2-7/8" tbg. & tagged @ 4569'. Could not get on RBP. POH w/tbg. & retrieving tool. RIH w/4-3/4" bit & DC's on 2-7/8" tbg. Tagged @ 4569'. Drld. f/4569'-4571'. Recovered sand.

03/26/97 Released RBP @ 4571' & POH. HLS perforated Grayburg perms. f/4200', 01', 10'-13', 4327', 28', 29', 35', 36', 37', 65', 68'-71', 74'-77' & 83' w/1 SPF (22 holes). Set RBP @ 4400' & RTTS pkr. @ 4195'. HES acidized Grayburg perms. 4200'-4383' w/3300 gals. 15% NE-FE acid & 44 ball sealers. Formation broke @ 3767#. Had good ball action. MTP 4419# @ 5.6 bpm. ATP 3340# @ 4.5 bpm. ISIP 2641#. 5 min. 2126#. 10 min. 1974#. 15 min. 1912#.

03/28/97 HES frac'd Grayburg perms. f/4200'-4383' w/8,000 gals. gelled water, 20,000 gals. 20# Delta Frac & 50,000# 16/30 Brown sand. MTP 4815# @ 47 bpm. ATP 3091# @ 45 bpm. ISIP 3798#. 5 min. 2768#. 10 min. 2560#. 15 min. 2610#.

03/31/97 RIH w/retrieving head & tbg. Tagged sand @ 4219'. Wash sand f/4219'-4400' top of RBP. Released RBP & POH.

04/01/97 RIH w/production string. MA @ 4698'. SN @ 4668'. TAC @ 4146'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mary Jo Turner TITLE Completion Department Date June 20, 1997

TYPE OR PRINT NAME Mary Jo Turner TELEPHONE NO. (505) 392-9797

(This space for State Use)

ORIGINAL SIGNED BY  
GARY WINK  
FIELD REP. ☒

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE June 20, 1997