

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Geology, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-34343
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 22993
7. Lease Name or Unit Agreement Name WEST HOBBS STATE UNIT
8. Well No. 1
9. Pool name or Wildcat Wildcat/Abo
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL: 3741' KB: 3784'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry
2. Name of Operator Ricks Exploration, Inc.
3. Address of Operator 5600 No. May, Suite 350, Oklahoma City, OK 73112
4. Well Location Unit Letter P : 1120' Feet From The South Line and 860' Feet From The East Line Section 8 Township 18S Range 37E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well is presently Temporarily Abandoned. If we proceed with plugging operations, they will be as follows: (TOC @3200')

100' plug 4084-3984' Cls H, 35' on top. Tbg 25 sx min., Cls H, tbg @4084'.
Base of salt formation 3150' w/tbg @3150', pump 25 sx min, Cls H. Top of salt formation 1800', w/tbg @1800', pump 25 sx min, Cls H. Top plug inside 5½" 10 sx min., Cls H.
San Andres: 5072-5084', CIBP @5040', 10' cmt on top; 5180-5200', 10' cmt on top.
Drinkard: 7700-7110', CIBP @7680', 10' cmt on top.
Abo: 8100-8110', CIBP @8080', 10' cmt on top; 8128-50', sqz holes, 40sx cmt.
Abo: 8342-72', CIBP @8330' w/10' cmt on top.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lynne Suchy TITLE Drilling Operations Asstnt DATE 6/3/98
TYPE OR PRINT NAME Lynne Suchy TELEPHONE NO. 405/840909

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: