TED STATES

N.M. il Cons. Division No. 1004-0135 March 31, 1993 ion and Serial No.

BUREAU OF LAND MANAGEMENT 1625 N. Fre Expires: March 3 SUNDRY NOTICES AND REPORTS ON WELLS Hobbs, NM 88240 NM-4605 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals 6. If Indian, Allottee or Trill SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreement) De Name
SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreemen	
1. Type of Well Unit Letter	Ū
Oil Gas Well Well Other 2. Name of Operator Querecho	ederal # 1
P.O. Box 5270 Hobbs, NM 88241 (505)393-5905 10. Field and Pool, or Exp 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Querecho Bone	9. API Well No. 30-025-34361 10. Field and Pool, or Exploratory Area Querecho Bone Springs
2310' FSL & 990' FEL, Sec.28,T-18S, R-32E 11. County or Parish, Stat Lea County, New	
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Intent Abandonment Change of Plans Recompletion New Construction	
Subsequent Report Plugging Back Non-Routine Fractur Casing Repair Water Shut-Off	ing
Image: Second	mpletion on Well

13. Describe Proposed or Completed Operations (Clearly state all pertinet details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markders and zones pertinent to this work.)*

10/25/2001 MIRU Marrs Pulling Unit. Bleed down Well and Nipple Up BOP. SWI Overnight.

10/26/2001 Work Tubing Anchor Loose. Pooh w/ 304 Joints of 2 7/8" 6.5# N-80 8-Round Tubing & TAC. RIH and Set CIBP @ 8820' RIH w/ Tubing to 8820'. SI Well & Shut down over weekend.

10/29/2001 Mix & Circulate 10# Mud. Spot 25sxs of Cement @ 8820' - 8580'. POOH and Laydown 2550' of Tubing. Nipple Down BOP & Wellhead. Weld On Pull Sub. SD Overnight.

10/30/2001 Rig up Casing Jacks. Obtain stretch on Casing. Showed to have 5100 +- of Free Pipe. TIH w/ Jet Cutter and Cut Casing @ TOC 6203' Work stuck wireline free and TOH leaving weight bars and Rope Socket in Hole. Work Casing w/ no success. TIH w/ Tubing to 6270' to Spot Cement. SI Overnight

10/31/2001 Mix & Circulate 10# Mud. Spot 25sxs @ 6270' - 6030'. POOH w/ Tubing laying down 1130'. WOC 2hrs and RIH w/ Wireline and Tag @ 5877'. (Steve Caffey w/ BLM & Terry Burke w/ MOC supervised and witnessed all above operations) RIH w/ Jet Cutter on Wireline and Cut Casing @ 5112'. Laydown 5 Joints of 5 1/2" 20# S95 LT&C Casing. Rig Down Casing Jacks. SDON.

11/01/2001 POOH w/ 114 Joints of 5 1/2" Casing SDON

11/02/2001 RIH w/ Tubing and Mix & Circulate 10# Mud. Spot 50sxs @ 5130' Pull 5 stands and laydown 175' & WOC. TIH and Tag cement @ 4956' (Witnessed by Steve Caffeyw/ BLM & Terry Burke w/ MOC) Laydown 700' and Spot 70sxs @ 4434'. POOH w/ Tubing and WOC. SDOW

11/05/2001 RIH w/ Tubing and Tag cement @ 4263' (Witnessed by Steve Caffeyw/ BLM & Terry Burke w/ MOC) POOH laying down 2250' or Lubing and Sput.oussed and a sput.oussed and a sput second and sput second an 11/05/2001 RIH w/ Tubing and Tag cement @ 4263' (Witnessed by Steve Caffeyw/ BLM & Terry Burke w/ MOC) POOH laying down 2250' of Tubing and Spot. 50 and 50 11/05/2001. Cut Off Wellhead. Set dry hole maker. Remove anchors & empty reserve pit and liner. RDMO Mayo Marr's Casing Pulling Inc.

		DEC 1	
14. I hereby certify that the foregoing is true and correct SignedBuhu	т _{itle} _Drlg Foreman	GARY GOUR BY PETROLEUM ENGINE 81/25/01	
(This space for Federal of State office use) Approved by Conditions of approval, if any:	Title	Date	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

I C ς

RECEIVED 2001 DEC 5 PM 1 16 DUNEAU OF LAND NUMT. CONTESEND FIELD OFFICE (