State of New Mexico	
Energy, Minerals & Natural Resources	Department

-

Submit 3 Copies to Appropriate District Office

-6

· • • •

DISTRICT I PO Box 1980, Hobbs, NM 88241-1980 OIL CONSERV	ATION DIVISION	ELL API NO.	
DISTRICT II Sauta Fa	D Box 2088 NM 87504-2088	<u></u>	18
PO Drawer DD, Artesia, NM 88211-0719	NW 87304-2088 5. h	ndicate Type of Lease	r0
DISTRICT III		STATE [] FEE 🔀
1000 Rio Brazos Rd., Aztec, NM 87410	6. 8	tate Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS C			
(DUNUT USE THIS FORM FOR PROPOSALS TO DRILL OP T			
	N FOR PERMIT"	ease Name or Unit Agreement Nam	ie
(FORM C-101) FOR SUCH PROPOSA	LS)		
OIL GAS		HOBBS "7"	
WELL WELL OTHER	DRY HOLE		
2. Name of Operator	8. W	ell No.	·
SAHARA OPERATING COM 3. Address of Operator	PANY	1	
	9. Pc	ool name or Wildcat	
P.O. Box 4130, Midland, Texas 79704 4. Well Location		Wildcat	
Unit Letter Lot 4 : 398 Feet From The Sol	uth Line and 384	Foot Draw The Foot	
Section 7 Township 18 Sou			Line
10. Elevation (Sho	Ith Range 38 East NM	<u>IPM Lea</u>	County
	3689' KB		
Check Appropriate Box to Indi	cate Nature of Notice, Report, or	Other Data	
NOTICE OF INTENTION TO:	SUBSE	EQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON			
TEMPORARILY ABANDON			
PULL OR ALTER CASING	COMMENCE DRILLING OPN		NDONMENT
	CASING TEST AND CEMENT	JOB [_]	
	()		
OTHER:	OTHER:		
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 1103	t details, and give pertinent dates, includi	ng estimated date of starting any p	roposed
 12. Describe Proposed or Completed Operations (Clearly state all pertinent work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" one 	t details, and give pertinent dates, includi	ng estimated date of starting any p	roposed
 12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" ope 3-5-99 Obtained plugging procedure from Gamma 	r details, and give pertinent dates, includi inhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and	ng estimated date of starting any p	roposed
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" ope 3-5-99 Obtained plugging procedure from Ga Plug # Depth to Bottom of Drill I	t details, and give pertinent dates, includi inhole. TD 7540'. 8-5/8" casing ary Wink, TIH Open ended and	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows:	
12. Describe Proposed or Completed Operations (Clearly state all pertinen. work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" ope 3-5-99 Obtained plugging procedure from Ga Plug # 1 7540'	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50	ng estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite	Comment
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" ope 3-5-99 Obtained plugging procedure from Ga Plug # Depth to Bottom of Drill I 1 7540' 2 7479'	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30	ng estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite	
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" ope 3-5-99 Obtained plugging procedure from Ga Plug # Depth to Bottom of Drill I 1 7540' 2 7479' 3 5695'	nhole. TD 7540'. 8-5/8" casing any Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50	ng estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite	Comment
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" ope 3-5-99 Obtained plugging procedure from Ga Plug # Depth to Bottom of Drill I 1 7540' 2 7479' 3 5695' 3-6-99 4	nhole. TD 7540'. 8-5/8" casing any Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2	Comment Tag 7480' no tag no tag
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" ope 3-5-99 Obtained plugging procedure from Ga Plug # Depth to Bottom of Drill I 1 7540' 2 7479' 3 5695' 3-6-99 4 5695' 6 5668'	nhole. TD 7540'. 8-5/8" casing any Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2	Comment Tag 7480' no tag
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 11033-4-99Finished logging & testing 7.875" ope3-5-99Obtained plugging procedure from GaPlug #Depth to Bottom of Drill I17540'27479'35695'55695'65668'74700'	nhole. TD 7540'. 8-5/8" casing any Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2	Comment Tag 7480' no tag no tag
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 11033-4-99Finished logging & testing 7.875" ope3-5-99Obtained plugging procedure from GaPlug #Depth to Bottom of Drill I17540'27479'35695'3-6-99455695'65668'74700'83750'	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 50 50 25	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2	Comment Tag 7480' no tag no tag
I2. Describe Proposed or Completed Operations (Clearly state all pertinen. work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" ope 3-5-99 Obtained plugging procedure from Ga Plug # Depth to Bottom of Drill I 1 1 7540' 2 2 7479' 3 3-6-99 4 5 5695' 6 6 5668' 7 7 4700' 8 8 3750' 9	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 25 25	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat	Comment Tag 7480' no tag no tag
I2. Describe Proposed or Completed Operations (Clearly state all pertinen. work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" ope 3-5-99 Obtained plugging procedure from Ga Plug # Depth to Bottom of Drill I 1 1 7540' 2 2 7479' 3 3-6-99 4 5 5695' 6 6 5668' 7 7 4700' 8 8 3750' 9 9 1800' 10	r details, and give pertiment dates, includi enhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 25 25 25	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat "C" neat	Comment Tag 7480' no tag no tag Tag 5670'
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 1103 $3-4-99$ Finished logging & testing 7.875" ope $3-5-99$ Obtained plugging procedure from GaPlug #Depth to Bottom of Drill I17540'27479'35695'55695'65668'74700'83750'91800'10450'1140'Cut off wellbead, weided on plate and inste	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 50 25 25 25 25 25 25	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat "C" neat	Comment Tag 7480' no tag no tag
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 1103 $3-4-99$ Finished logging & testing 7.875" ope $3-5-99$ Obtained plugging procedure from GaPlug #Depth to Bottom of Drill I17540'27479'35695'55695'65668'74700'83750'91800'10450'1140'Cut off wellbead, weided on plate and inste	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 50 25 25 25 25 25 25	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat "C" neat	Comment Tag 7480' no tag no tag Tag 5670'
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 1103 $3-4-99$ Finished logging & testing 7.875" ope $3-5-99$ Obtained plugging procedure from GaPlug #Depth to Bottom of Drill I17540'27479'35695'3-6-99455695'65668'74700'83750'91800'10450'1140'	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 50 25 25 25 25 25 25	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat "C" neat	Comment Tag 7480' no tag no tag Tag 5670'
12. Describe Proposed or Completed Operations (Clearly state all pertinen, work) SEE RULE 1103 $3-4-99$ Finished logging & testing 7.875" ope $3-5-99$ Obtained plugging procedure from GaPlug #Depth to Bottom of Drill I17540'27479'35695'55695'65668'74700'83750'91800'10450'1140'Cut off wellbead, weided on plate and inste	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 25 25 10 Iled dry hole marker. Rig has r faiythowledge and belief.	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat "C" neat	Comment Tag 7480' no tag no tag Tag 5670'
12. Describe Proposed or Completed Operations (Clearly state all pertinen. work) SEE RULE 11033-4-99Finished logging & testing 7.875" ope 3-5-993-5-99Obtained plugging procedure from Ga Plug # Depth to Bottom of Drill I 117540' 227479' 33-6-99455695' 665668' 774700' 883750' 991800' 1010450' 1140'Cut off wellhead, welded on plate and insta 1 hereby certify that the information above/s true and complete to the best of	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 50 25 25 25 25 25 25	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat "C" neat "C" neat "C" neat top not moved yet.	Comment Tag 7480' no tag no tag Tag 5670'
12. Describe Proposed or Completed Operations (Clearly state all pertinen. work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" operations of the plugging procedure from Garden Plug # Depth to Bottom of Drill I 1 7540' 2 7479' 3 5695' 3-6-99 4 5 5695' 6 5668' 7 4700' 8 3750' 9 1800' 10 450' 11 40' Cut off wellhead, welded on plate and insta I hereby certify that the information above?s true and complete to the best operations above?s true SIGNATURE 10	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 25 25 10 Iled dry hole marker. Rig has r faiythowledge and belief.	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat "C" neat "C" neat "C" neat top not moved yet.	Comment Tag 7480' no tag no tag Tag 5670' of plug @ surf
12. Describe Proposed or Completed Operations (Clearly state all pertinen. work) SEE RULE 11033-4-99Finished logging & testing 7.875" ope 3-5-993-5-99Obtained plugging procedure from Ga Plug # Depth to Bottom of Drill I 117540' 227479' 33-6-99455695' 665668' 774700' 883750' 991800' 1010450' 1140'Cut off wellhead, welded on plate and insta 1 hereby certify that the information above/s true and complete to the best of	r details, and give pertinent dates, includi enhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 25 10 Iled dry hole marker. Rig has r faily fluowledge and belief.	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat "C" neat "C" neat "C" neat top not moved yet.	Comment Tag 7480' no tag no tag Tag 5670' of plug @ surf 3-15-99
12. Describe Proposed or Completed Operations (Clearly state all pertinen. work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" operations of the plugging procedure from Garden Plug # Depth to Bottom of Drill I 1 7540' 2 7479' 3 5695' 3-6-99 4 5 5695' 6 5668' 7 4700' 8 3750' 9 1800' 10 450' 11 40' Cut off wellhead, welded on plate and insta I hereby certify that the information above?s true and complete to the best operations above?s true SIGNATURE 10	r details, and give pertinent dates, includi enhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 25 10 Iled dry hole marker. Rig has r faily fluowledge and belief.	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" neat "DATE	Comment Tag 7480' no tag no tag Tag 5670' of plug @ surf 3-15-99
12. Describe Proposed or Completed Operations (Clearly state all pertinen. work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" operations of the plugging procedure from Garden Plug # Depth to Bottom of Drill I 1 7540' 2 7479' 3 5695' 3-6-99 4 5 5695' 6 5668' 7 4700' 8 3750' 9 1800' 10 450' 11 40' Cut off wellhead, welded on plate and insta I hereby certify that the information above is the and complete to the best of SIGNATURE TYPE OR PRINT NAME	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 25 10 Iled dry hole marker. Rig has r faiy/fluowledge and belief.	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat "C" neat "C" neat "C" neat top not moved yet. DATE	Comment Tag 7480' no tag no tag Tag 5670' of plug @ surf
12. Describe Proposed or Completed Operations (Clearly state all pertinen. work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" operations of the plugging procedure from Garden Plug # Depth to Bottom of Drill I 1 7540' 2 7479' 3 5695' 3-6-99 4 5 5695' 6 5668' 7 4700' 8 3750' 9 1800' 10 450' 11 40' Cut off wellhead, welded on plate and insta I hereby certify that the information above is the and complete to the best of SIGNATURE TYPE OR PRINT NAME	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 25 25 10 Iled dry hole marker. Rig has r faiy knowledge and belief.	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat "C" neat "C" neat "C" neat top not moved yet. DATE	Comment Tag 7480' no tag no tag Tag 5670' of plug @ surf 3-15-99
12. Describe Proposed or Completed Operations (Clearly state all pertinen. work) SEE RULE 1103 3-4-99 Finished logging & testing 7.875" ope 3-5-99 Obtained plugging procedure from Ga Plug # Depth to Bottom of Drill I 1 7540' 2 7479' 3 5695' 3-6-99 3-6-99 4 5695' 5 5695' 6 5668' 7 4700' 8 3750' 9 1800' 10 450' 11 40' Cut off wellhead, welded on plate and insta 1 hereby certify that the information above is the and complete to the best of SIGNATURE TYPE OR PRINT NAME TYPE OR PRINT NAME Robert McAlpine (This space for State Use) A	nhole. TD 7540'. 8-5/8" casing ary Wink. TIH Open ended and Pipe Sacks of Cement 50 30 50 50 50 25 50 25 25 10 Iled dry hole marker. Rig has r faiy/fluowledge and belief.	ing estimated date of starting any p @ 3700', 13-3/8" @ 400'. I set plugs as follows: Cement Type "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "H" w/10% Gilsonite "C" w/3% CaCL2 "C" w/3% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" w/2% CaCL2 "C" neat "C" neat "C" neat "C" neat "C" neat top not moved yet. DATE	Comment Tag 7480' no tag no tag Tag 5670' of plug @ surf

10