

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-34643
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NORTH HOBS G/SA UNIT
8. Well No. 521
9. Pool name or Wildcat HOBS; GRAYBURG - SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Altura Energy LTD	
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294	
4. Well Location Unit Letter C : 990 Feet From The NORTH Line and 1500 Feet From The WEST Line Section 33 Township 18-S Range 38-E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3646' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: **Rm 5-1/2" Casing** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/16/99: Rm 103 jts. of 5-1/2", 15.5#, J-55, LTC casing with 11 centralizers and set at 4400'. Pump first stage cement, 395 sx. Premium Plus, plug down, and circulate 0 sx. to pit. Circulate through DV tool (@3487') between stages. Pump second stage cement, 810 sx. Inner Fill Cl. C, plug down, and circulate 0 sx. to pit. Set slips, nipple down, and cut off.

Release drilling rig at 1:30 a.m., 7/17/99.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE **BUSINESS ANALYST (SG)** DATE **7/20/99**
TYPE OR PRINT NAME **MARK STEPHENS** TELEPHONE NO. **281-552-1158**

(This space for State use)
ORIGINAL SIGNED BY
GARY WINK
FIELD REP. #

APPROVED BY _____ TITLE _____ DATE **JUL 28 1999**

CONDITIONS OF APPROVAL, IF ANY: