

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

FILE IN TRIPLICATE

**OIL CONSERVATION DIVISION**

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

2040 Pacheco St.  
Santa Fe, NM 87505

DISTRICT II  
811 S. 1st Street, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd. Aztec, NM 87410

WELL API NO.	30-025-34907
5. Indicate Type of Lease	FED <input type="checkbox"/> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTH HOBBS (G/SA) UNIT
8. Well No.	512
9. Pool name or Wildcat	HOBBS (G/SA)

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)	
1. Type of Well:	Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator	Oxy Permian, Ltd.
3. Address of Operator	1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200
4. Well Location	Unit Letter <u>F</u> : <u>2164</u> Feet From The <u>NORTH</u> Line and <u>2054</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>18S</u> Range <u>38E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT GR, etc.)	3631 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG & ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: Open Additional Pay - San Andres ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  
SEE RULE 1103.

1. RUPU. Pull production equipment.
2. Set CIBP at 4250'.
3. Perforate the San Andres Zone at the following intervals; 4081-85, 4090-96.
4. 2 JSPF and 180 deg spiral phasing.
5. Stimulate new perms w/500 g 15% NEFE HCL acid.
6. RIH w/REDA ESP equipment on 121 jts 2-7/8" tbg.
7. RDPU. Clean Location.

Rig Up Date: 11/12/2002  
Rig Down Date: 11/14/2002

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert Gilbert TITLE SR. ENGR TECH DATE 11/17/2002  
TYPE OR PRINT NAME ROBERT GILBERT TELEPHONE NO. 505/397-8206

(This space for State Use)

APPROVED BY \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL IF ANY:

OC FIELD REPRESENTATIVE  
DEC 09 2002