

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-34944
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	295
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3973'

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMITS  
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator  
205 E. Bender, HOBBS, NM 88240

4. Well Location  
Unit Letter A : 669 Feet From The NORTH Line and 10 Feet From The EAST Line  
Section 6 Township 18-S Range 35-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3973'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☒ FRAC UPPER SAN ANDRES

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-29-00: MIRU. NDWH. NUBOP. TBG @ 4778. TIH W/BITR, CSG SCRAPER. PU TBG & STOP BIT @ 1214'.  
8-30-00: KILL WELL W/60 BBLs. PU WS. TAG @ 4816' (PBD 4818') TIH OPEN ENDED W/TBG TO 4340'.  
8-31-00: CIRC HLE W/150 BBLs FR WTR & SPOT 5800# 20/40 SAND. PULL TBG TO 2480'. TIH & TAG SAND @ 4186'. WASH OUT SAND BRIDGE 4186-4370'. TAG SAND @ 4570'. PULL TBG TO 4340'. SPOT 1950# 20/40 SAND. PULL TBG TO 1861'. UNLOAD, RACK, TALLY 140 JTS FRAC TBG.  
9-01-00: TIH & TAG SAND @ 4444'.  
9-05-00: CHANGE RAMS IN BOP TO 3 1/2". TIH W/FRAC PKR, SN, FRAC TBG. TEST TBG TOL 8500 PSI. SET PKR @ 4233'. LOAD/PSI CSG TO 1000 PSI-OK.  
9-06-00: FRAC VGSA PERFS 4352-4435' W/48,000 GALS YF-135 & 52,200# 16/30 BRADY SAND & 42,040# 16/30 SAND. PUMP 22,000 GALS YF-135 PAD, 2000 GALS YF-135 W/2 PPG 16/30 BRADY SAND, 16000 GALS YF-135 W/3 PPG 16/30 SAND, 2000 GALS YF-135 W/4 PPG 16/30 SAND, 2000 GALS YF-135 W/5 PPG 16/30 SAND, 4000 GALS YF-135 W/6 PPG 16/30 SAND.  
9-07-00: FLOW WELL DN. REL PKR @ 4233'. CIRC W/FRESH WTR. TIH W/BIT, DC'S & TBG TO 4390'. PULL BIT TO 4337'.  
9-08-00: C/O SAND 4390-4818.  
9-11-00: CIRC W/130 BFW. LOWER TBG. CHECK FOR FILL. TAG TD @ 4818'. TIH W/GAS SEPR, SN, TBG, TAC, TBG. SN @ 4772'. TAC @ 4198'. NDBOP. SET TAC W/13 PTS. NUWH. TIH W/PUMP, K-BARS, RDS.  
9-12-00: LOAD/TEST TBG. 500 PSI-OK. CHECK PUMP ACTION -WOULD NOT PUMP. TIH W/PUMP #2. PUMPING GOOD.  
9-13-00: WELL NOT PUMPING. TIH W/SN, TBG, TAC. NDBOP. SET TAC. NUWH. SET @ 11' KB. SN @ 4773'. TAC @ 4198. TIH W/NIP, PUMP & RDS. LOAD/TEST-OK. PUMPING @ 4:00 PM.  
9-14-00: RIG DOWN.  
10-04-00: ON 24 HR OPT. PUMPED 224 BO, 14 BW, 80 MCF.  
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 10/11/00

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY: \_\_\_\_\_ TITLE \_\_\_\_\_

DATE \_\_\_\_\_