State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE OIL CONSERVATION DIVISION									
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St. Santa Fe. NM 87505			WELL API NO. 30-025-34983					
<u>DISTRICT II</u>				5. Indicate Type of Lease				_	
811 S. 1st Street, Artesia, NM 88210				FED	STATE [F	EE X		
<u>DISTRICT III</u>				6. State Oil & 0	Gas Lease No.	•			
1000 Rio Brazos Rd. Aztec, NM 87410						,,,,,,,,			
SUNDRY NOTICES AND REPORTS ON WELLS									
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)				7. Lease Name or Unit Agreement Name NORTH HOBBS . G.S.A. UNIT.					
1. Type of Well:					(2120) (100, 310)	. 71.			
Oil Well X	Gas Well Other								
2. Name of Operator					8. Well No. 713				
ALTURA ENERGY LTD. 3. Address of Operator					Wildeat	LIANT	413434	_	
1017 W. Stanolind Rd., HOBBS, NM 88240 505 397-8200					r wildeat	HOBBS	(G/SA)		
4. Well Location	30270	75 371-6200						-	
Unit Letter B : 1196	Feet From The NORTH	Line and	1823 Fee	et From The	EAST	Line			
Section 30	Township 18S	F	Range 38E	S NMP	M	LEA	County		
	10. Elevation (Show whether L	F, RKB, RT GR, etc.))						
	3652 GL								
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:									
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL	WORK		ALTERING	CASING		-	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DRILLING OPN			NS.	PLUG & AE		ENT	\equiv	
PULL OR ALTER CASING	CASING TEST AND CEMEN								
OTHER: New Well Completion X OTHER:				000			_	_	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinen									
 Describe Proposed or Completed Operations SEE RULE 1103. 	s (Clearly state all pertinent detail	is, and give pertinent	dates, including e	estimated date of sta	arting any propo	sed work)		_	
AND THE RESERVE OF THE STATE OF									
1. Tag PBTD.									
2. Spot Acid.									
3. Perforate 4150-43004. Run production equipment.									
4. Kun production equipment.									
^									
Thurshy surification to Laborate A 1 & 1 & 2	a and Amerika a day a day	1-1							
I hereby certify that the information above is tru	e and complete to the best of my ki	nowledge and belief.				,			
SIGNATURE A A STORY		TITLE _	PROD ENGR		DATE	6-2	7-00		
TYPE OR PRINT NAME D. NELSON		_		TEI	LEPHONE NO.	505 39	7-8200	_	
(This space for State Use)	<u> </u>			<u> </u>				=	
						,	1177		
APPROVED BY	<u> </u>	TITLE _		ILL'AME	DATE	V		—	
CONDITIONS OF APPROVAL IF ANY:	* *								

