

FILE IN TRIPLICATE

# OIL CONSERVATION DIVISION

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

2040 Pacheco St.  
Santa Fe, NM 87505

DISTRICT II  
811 S. 1st Street, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

WELL API NO.	30-025-35376
5. Indicate Type of Lease	FED <input type="checkbox"/> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT
2. Name of Operator Occidental Permian Ltd.	8. Well No. 643
3. Address of Operator 1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200	9. Pool name or Wildcat HOBBS (G/SA)
4. Well Location Unit Letter <u>I</u> : <u>2350</u> Feet From The <u>SOUTH</u> Line and <u>1125</u> Feet From The <u>EAST</u> Line Section <u>29</u> Township <u>18S</u> Range <u>38E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3644 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<p><b>NOTICE OF INTENTION TO:</b></p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>	<p><b>SUBSEQUENT REPORT OF:</b></p> <p>REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG &amp; ABANDONMENT <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER: <u>New Well Completion</u> <input checked="" type="checkbox"/></p>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RUPU. Drill out DV Tool @3536'. Clean out to PBTD @4355'.
2. Perforate 4096—4274. Using 4" guns, 4 JSPF, 90 degree phased.
3. Stimulate w/2200 gals 15% HCL Acid.
4. RIH w/ REDA ESP equipment on 130 jts 2-7/8" tbg. Bottom of tbg @4003'.
5. RDPU. Clean Location.

Rig Up Date: 04/23/2001  
Rig Down Date: 04/26/2001

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Robert Gilbert TITLE SR. ENGR. TECH DATE 05/10/2001  
TYPE OR PRINT NAME ROBERT GILBERT TELEPHONE NO. 505/397-8206

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE CHIEF DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL IF ANY:

3