State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

FILE IN TRIPLICATE	OIL C	'ONSERV	ATION	DIVISIO	N				
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	2040 Pacheco St. Santa Fe, NM 87505				WELL API N	WELL API NO. 30-025-35450			
<u>DISTRICT II</u>					5. Indicate Ty	5. Indicate Type of Lease			
811 S. 1st Street, Artesia, NM 88210					FED	STATE	X FEE		
<u>DISTRICT III</u>					6. State Oil &	Gas Lease No.			
1000 Rio Brazos Rd, Aztee, NM 87410									
SUNDRY NOTICES AND REPORTS ON WELLS									
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)						7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT			
1. Type of Well:						ODS (GISA) (JINII		
Oil Well X	Gas Well	Other							
2. Name of Operator				·	8. Well No.	612			
Occidental Permian Ltd. 3. Address of Operator					9. Pool name	or Wildoot	HODDU (C)	CAN	
3. Address of Operator 1017 W. Stanolind Rd., HOBB	S NM 88240	505/30	7-8200		9. Pool name	or windcar	HOBBS (G/S	SA)	
4. Well Location	5, NW 88240	505/5/	77-8200			**			
Unit Letter <u>E</u> : <u>2220</u>	Feet From The	NORTH	Line and	406	Feet From The	WEST	Line		
Section 24	Township	18S		Range	37E NN	IPM	LEA Cour	nty	
	10. Elevation (Show 3610GL	whether DF, RI	KB, KT GR, et	z.)					
11. CI	neck Appropriate Box to	o Indicate Na	ture of No	ice, Report	, or Other Data	- William Control	<u> </u>		
NOTICE OF I	NTENTION TO:			S	SUBSEQUENT	REPORT OF	: :		
PERFORM REMEDIAL WORK	PLUG AND ABAND	ON	REMEDIA	L WORK		ALTERING	CASING		
TEMPORARILY ABANDON	CHANGE PLANS		COMMEN	CE DRILLING	G OPNS.	PLUG & AI	BANDONMENT	Γ-	
PULL OR ALTER CASING	- -		CASING -	TEST AND C	EMENT JOB]		•	
OTHER: New Well Completion	_	X	OTHER:		<u> </u>	1		<u></u>	
			1						
12. Describe Proposed or Completed Oper SEE RULE 1103.	ations (Clearly state all pertu	nent details, and	d give pertine.	it dates, includ	ding estimated date of :	starting any propo	sed work)		
L. DO DV Tool at 3511.									
2. Tag PBTD.						.7282	2		
3. Perforate 4216-4327.						1.31.1202	33037		
4. Acid Stimulate.									
5. Run production equipment.					#	a	93037		
					* *		음을 🖺		
					1 4 6		是一点	I	
					137	当当	<u> </u>		
					\c;	,	3/		
						ŠO.			
						X 2 2 1 2 2 2			
			1 11 1				· 		
Thereby certify that the information above	is true and complete to the be	est of my knowie	age and belle	l.					
SIGNATURE			TITLE	PROD EN		DATE			
TYPE OR PRINT NAME D. NELS	ON			·	T	ELEPHONE NO.	505/397-820)0	
(This space for State Use)									
APPROVED BY			TITLE			DATE			
CONDITIONS OF APPROVAL IF ANY:									