

Ne

State of New Mexico
Energy, Minerals and Natural Resources DepartmentForm C-103
Revised 1-1-89

FILE IN TRIPLICATE

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs, NM 882402040 Pacheco St.
Santa Fe, NM 87505DISTRICT II
811 S. 1st Street, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.	30-025-35534
5. Indicate Type of Lease	FED <input type="checkbox"/> STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NORTH HOBBS (G/SA) UNIT Surface Location Section 33 Bottom Hole Location Section 32
8. Well No.	844
9. Pool name or Wildcat	HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101 FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Occidental Permian Ltd.	
3. Address of Operator 1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200	
4. Well Location Unit Letter M : 1051 Feet From The SOUTH Line and 217 Feet From The WEST Line Section 33 Township 18S Range 38E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3635 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: NEW WELL COMPLETION <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103.

1. RUPU. INSTALL BOP.
2. DRILL OUT DV TOOL @3523'. CLEAN OUT TO PBTD@ 4340'.
3. PERFORATE THE SAN ANDRES FROM 4106' TO 4258'.
4. STIMULATE W/ 2000 G 15% HCL ACID.
5. RUH W/REDA ESP EQUIPMENTON 124 JTS 2-7/8" TBG.

WELL IS ON PRODUCTION 05/26/2001.

RIG UP DATE: 05/21/2001
RIG DOWN DATE: 05/25/2001

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE	<u>Robert Gilbert</u>	TITLE	<u>SR. ENGR TECH.</u>	DATE	<u>08/02/2001</u>
TYPE OR PRINT NAME	<u>ROBERT GILBERT</u>	TELEPHONE NO.	<u>505/397-8206</u>		

(This space for State Use)

APPROVED BY	<u>Robert Gilbert</u>	TITLE	<u>Sr. Engr Tech</u>	DATE	<u>08/02/2001</u>
CONDITIONS OF APPROVAL IF ANY:					

5
1

