Form 3160-5 (November 1994)

## UNITED STATES DEPARTME OF THE INTERIOR BUREAU OF LAND MANAGEMENT

N.M. Oil Cons. Division 16

25 N	. Fr	`ch	Dr.	FORM APPROV OMB No. 1004-0 Expires July 31, 1
hha	AILA	ဝဝင်္ဂ	40	

SUNDA	Y NOTICES AND REPORTS ON	I IUUUS, IXIVI OO	240 Cease Serial No. NM 104685			
Do not use the abandoned we	6. If Indian, Allottee or Tribe Name					
SUBMIT IN TR	7. If Unit or CA/Agreement, Name and/or No.					
1. Type of Well  Oil Well  Gas Well						
2. Name of Operator	8. Well Name and No.					
Lynx Petroleum	Hawkeye 7 Fed. #2 9. API Well No.					
Ja. Address D. O. Boy 1700	30-025-35661					
P.O. Box 1708,  4. Location of Well (Footage, Sec.	10. Field and Pool, or Exploratory Area					
U.L. "J", 1650'	Lusk; Strawn 11. County or Parish, State					
Section 7, $T-19$	line of the same of the same					
	Lea County, NM					
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize Deepe	n Production (Star	t/Resume)			
_	Alter Casing Fractu	re Treat Reclamation	Well Integrity			
Subsequent Report	_	Construction    Recomplete	Other			
Final Abandonment Notice		nd Abandon 🔲 Temporarily Ab	andon			
	Convert to Injection Plug E	· · · · · · · · · · · · · · · · · · ·	ny proposed work and approximate duration thereo:			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zoner. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLMBIA. Required subsequent reports shall be filed only offilowing completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed one testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  We have decided to test the Strawn before plugging back to the Bone Spring. A Sundry was sent in yesterday to plug back and test the Bone Spring without testing the Strawn. The following procedure will now be used:  1. Set a CIBP at 12205' with 35' of cement on top.  2. Perforate the Strawn 11308'-16'.  3. Swab test and treat as necessary to evaluate the Strawn.  4. If the Strawn is not commercially productive, a CIBP will be set at 11250' with 35' of cement on top, and we will test the Bone Spring.  APPROVED  14. Thereby certify that the foregoing is true and correct						
Name (Printed/Typed)	g is true and correct	Title	HW 0.1 mm			
Marg Wise		President	JUN 2 1 2002			
Marc Win		Date 6/20/02	GARY GOURLEY			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE PETROLEUM ENGINEER						
Approved by		Title	Date			
Conditions of approval, if any, are a certify that the applicant holds legal which would entitle the applicant to c	ttached. Approval of this notice does not we or equitable title to those rights in the sub- onduct operations thereon.	varrant or Office ject lease	1/			
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.						