

3 Copies
DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.

30-025-35678

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.

28798

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

STATE VII

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Ricks Exploration, Inc.

8. Well No.

7

3. Address of Operator

210 Park Ave., Suite 3000

9. Pool name or Wildcat

Vacuum - Atoka, Morrow North

4. Well Location

Unit Letter A : 660' Feet From The North Line and 660' Feet From The East Line

Section 1 Township 17S Range 34E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

GL: 4033'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: Add perforations ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RU S/L Unit. Run in hole w/GR and tag TOF to verify W/L fish is still @12070' in the 2-3/8" tbg string. Set collar stop and W/L plug @12000'. RU W/L and perforate 4 holes in 2-3/8" tbg., 1 jt above W/L plug @12000'. Swab FL to 4000'. Release Retrievable Packer & TOH w/2-3/8" production string. RU W/L, tag Profile Nipple in 2-3/8" tailpipe below permanent Packer @12446', set W/L plug just above Nipple. TIH w/Model R Retrievable Packer on 2-3/8" tbg to 12298', & circ. Set Packer and pressure test plug in permanent Packer. Release Packer, spot acid from 12298-9200'. TOH w/tbg & Packer. RU W/L and perforate interval from 12280-12298', w/3-1/8" csg guns, 4 SPF, 90 deg phasing. TIH w/X-Nipple (PX plug in place), 10' Sub, AS1X Retrievable Packer, set @12200'+/-. Acidize, swab, & test. Evaluate results and frac if necessary. Return well to production. Procedure to be completed in September, 2002, or as soon as possible.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Lynne Suchy

TITLE

Drilling Asstnt

DATE 8/21/02

TYPE OR PRINT NAME

Lynne Suchy

TELEPHONE NO. 405/516-110

(This space for State Use)

ORIGINAL SIGNED BY
GARY W. WINK
QC FIELD REPRESENTATIVE / STATE MANAGER

TITLE

DATE AUG 26 2002

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY: