

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. 8910086380 LP-061155-17
2. NAME OF OPERATOR C.E. LARUE AND B.N. MUNCY, JR.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR PO BOX 1370 ARTESIA, NM 88211-1370	7. UNIT AGREEMENT NAME PEARSALL QUEEN SAND UNIT
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FNL & 1980' FEL SECTION 5 T18S, R32E	8. FARM OR LEASE NAME
14. PERMIT NO. 30-025-00843	9. WELL NO. TRACT 3 WELL 2
15. ELEVATIONS (Show whether OF, RT, GR, etc.)	10. FIELD AND POOL, OR WILDCAT PEARSALL QUEEN
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SECTION 5, T18S, R32E
	12. COUNTY OR PARISH LEA
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PROPOSE TO PLUG AND ABANDON THIS WELL.

OUR RECORDS INDICATE THAT 7" CASING WAS SET AT 3550' W/100 SACKS CEMENT. TOP OF CEMENT AT 2398'. WELL PRODUCED OPEN HOLE FROM 3550' TO 3780'. 7" CASING IS COLLAPSED AT @ 2350'. 3 ATTEMPTS HAVE BEEN MADE TO CLEAN OUT BACK TO BOTTOM, BUT INSTEAD WE GO OUTSIDE THE CASING.

PROPOSE TO SET 50 SACK PLUG AT COLLAPSING POINT (@ 2350'). CUT AND PULL CASING AT FREE POINT. SET 50 SACK PLUG IN AND OUT OF 7" STUB. (woc & tag)

SET 50 SACK PLUG IN AND OUT OF 10 3/4" SHOE AT 600'. (woc & tag)

SET 20 SACK PLUG AT SURFACE.

MUD BETWEEN ALL PLUGS. INSTALL DRY HOLE MARKER. CLEAN LOCATION.

18. I hereby certify that the foregoing is true and correct

SIGNED <u>[Signature]</u>	TITLE OPERATOR	DATE 2-9-96
(This space for Federal or State office use)		
APPROVED BY (ORIG. SCD.) JOE G. LARA	TITLE PETROLEUM ENGINEER	DATE 4/8/96
CONDITIONS OF APPROVAL, IF ANY:		

See attached. Also tag plugs @ 7" bsg. stub & 10 3/4" csg. shoe.

*See Instructions on Reverse Side