

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER Dry Hole		5. LEASE DESIGNATION AND SERIAL NO. LC064098
2. NAME OF OPERATOR C.E. LaRue and B.N. Muncy, Jr.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR PO Box 196 Artesia, NM 88210		7. UNIT AGREEMENT NAME Pearsall Queen Sand Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 990' FSL, 1650' FWL Section 5, T18S, R32E		8. FARM OR LEASE NAME Walker A
14. PERMIT NO. Not Issued		9. WELL NO. 2
15. ELEVATIONS (Show whether DF, RT, GR, etc.) GL 3817		10. FIELD AND POOL, OR WILDCAT Pearsall Queen
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 5, T18S, R32E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:


TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Propose to plug and abandon by cleaning out to original TD of 3741'. Set 100' cement plug at bottom, set 100' cement plug at 2350', set cement plug from 1210' to surface (casing shoe at 1160'). Clean up location, fill pits, set dry hole marker, rip pad and access road and re-seed according to specifications.



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWell, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operator

DATE 4/21/82

(This space for Federal or State use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APR 26 1982

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side

RECEIVED

APR 27 1984

O.C.D.
HOBBS OFFICE