| | UNITED STATES SUBMIT IN TRIPLICATIVE (Other instructions | Form approved. Budget Bureau No. 42-R1424. |
|--|---|--|
| | DEPARTMENT OF THE INTERIOR (Other Instructions (GEOLOGICAL SURVEY & 6 | 5. LEASE DESIGNATION AND SERIAL NO. LC 064009 (b) |
| | HINDRY OF RIVER SANS. CO. | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| 1 | SUNDRY NOTICES AND REPORTS ON WELLS not use this form for proposals to drill or to deepen or the fact to a different reservoir. Use "APPLICATION WOR PERMIT TO THE POTOSALS.) | |
| _ | 7 (AS [7] | 7. UNIT AGREEMENT NAME |
| WELL OTHER WIW | | YOUNG UNIT |
| | MONT OIL COMPANY | |
| JRESS OF OPERATOR | | 9. WELL NO. |
| P. C. BOX 1305, ARYESIA, NEW MEXICO 88210 OCATION OF WILL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface | | 1 |
| | | 10. F.ELD AND POOL, OR WILDCAT |
| | | 11. SEC., T., R., M., OR BLK. AND |
| 608 ESI | & 660° FWL of Sec. 9; T-18S; R-32E | SURVEY OR AREA |
| | | Sec. 9-18S-32E NAPM 12. COUNTY OR PARISH 13. STATE |
| 14, PERMIT N | 6. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) | |
| 1.0 | | Lea New Mexico |
| 16. | Check Appropriate Box To Indicate Nature of Notice, Report, or C | |
| | NOTICE OF INTENTION TO: SUBSEQU | ENT REPORT OF: |
| | TER SHUT-OFF PULL OR ALTER CASING WATER SHUT-OFF | REPAIRING WELL |
| FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING | | ALTERING CASING ABANDONMENT* |
| REPAIR A | Convert to | o Injection |
| (Other) | (Note: Report results Completion or Recompl | of multiple completion on Well etion Report and Log form.) |
| propose | PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, st work. If well is directionally drilled, give subsurface locations and measured and true vertice this work.) * | including estimated date of starting any idepths for all markers and zones perti- |
| This wel | I was cleaned out perforated and put on injection as follows: | OWS: |
| 3- 23 - 69 | Pulled rods, pump and tubing | |
| 3 - 25 - 69 | 9 Ran 5" sand pump and cleaned out. | |
| 4-11-69 | Start injection at 400 BPD at 150 psi | |
| 4-17-69 | Perforated 3797-3801 with NCF II jet charges 2 per foot. Return well to injection | |
| 4-24-69 | Run 2" tubing with 5 $1/2$ " x 2" totem tension packer set a injection down tubing. | et 3667° and start |
| | Injection first five days averaged 500 BPD at 1400 psi. | |
| | | |
| | | |
| | | |
| | | |
| 18. I hereby | certify that the foregoing is true and correct | |
| SIGNER | Towns Reflection Division Superintendent | t5/28/69 |
| | ce for Federal or State office use) | |
| , ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ | en e | |

*See Instructions on Reverse Side

TITLE _

dels

__ DATE __