Dec. 1973	Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEL OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	West Tonto Deep Unit
1. oil $\Box$ gas $XX$ other	9. WELL NO.
2. NAME OF OPERATOR	<u> </u>
Amoco Production Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Wildcat Strawn
P. O. Box 68 Hobbs, NM 88240	11. SEC., T., R., M., OR BLK. AND SURVEY C AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	18-19-33
below.) AT SURFACE: 1980' FNL & 690' FWL,	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Section 18 (Unit E, SW/4,	Lea NM
AT TOTAL DEPTH: NW/4)	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WE
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	263 Fill
TEST WATER SHUT OFF	
SHOOT OR ACIDIZE	) 1CE() (NOTE: Bepert results of multiple completion or zo GICAL SUBMAge on Form 9-330.) IEW MEXICO
PULL OR ALTER CASING	CICAL SUCHAnge on Form 9-330.)
MULTIPLE COMPLETE	GICAL SUCHARGE ON Form 9-330.) IEW MEXICO
CHANGE ZONES	
ABANDON*	

1.4

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to recomplete to the Strawn per the following procedure: Set cement retainer at 6720'. Squeeze perfs 6751'-66' and 6780'-94' with 350 sx Class H cement. WOC, drill out cement and test squeeze. Drill out cement retainers at 6827' and 6950'. Drill out bridge plugs capped with 35' cement at 10,720' and 10,900'. Set cement retainer at 10,915'. Squeeze perfs 10,948'-10,960' with 300 sx Class H cement. WOC, drill out cement, and test squeeze. Spot 210 gal 7½% HCL acid 12,346'-12,382'. Perforate 12,346'-12,362' and 12-376'-12,382' with 2 JSPF. Set packer at approx. 12,200'. Acidize, swab backload, and evaluate productivity.

Subsurface Safety Valve: Manu. and Type	Set @	Ft.
18. I hereby certify that the foregoing is true and correct		
SIGNED BOLLAUS TITLE ASST. Adm. Analystate	2-2 <b>2-</b> 80	:
APPROVED: for Federal or State office use)		,,,,,
APPROVED BY TITLE DATE CONDITIONS OF APPROVAL, FEBS 2 1980		
APPROVED BY TITLE DATE CONDITIONS OF APPROVAL, FEBY 2 1980 0+4-USGS-F T-HOU 1-SUSP 1-BD ACTING DISTRICT ENGINEER 'See Instructions on Reverse Side		