

Heaving plug—Material ..... Length ..... Depth set .....  
 Adapters—Material ..... Size .....

### SHOOTING RECORD

Size	Shell used	Explosive used	Quantity	Date	Depth shot	Depth cleaned out

### TOOLS USED

Rotary tools were used from 0 feet to feet, and from feet to feet

Cable tools were used from feet to feet, and from feet to feet

### DATES

....., 19..... Put to producing **Plugged & abandoned** 19.....

The production for the first 24 hours was ..... barrels of fluid of which .....% was oil: .....% emulsion; .....% water; and .....% sediment. Gravity, °Bé. ....

If gas well, cu. ft. per 24 hours ..... Gallons gasoline per 1,000 cu. ft. of gas .....

Rock pressure, lbs. per sq. in. ....

### EMPLOYEES

C. L. Wilson ..... Driller  
 C. E. Pierce ..... Driller  
 W. P. Yaws ..... Driller

### FORMATION RECORD

FROM—	TO—	TOTAL FEET	FORMATION
0	1190	1190	Red Bed
1190	1250	60	Red Bed & Anhy
1250	1340	n 90	Anhydrite
1340	2860	1520	Salt & Anhydrite
2860	2947	37	Anhydrite (TD)

(OVER)

13094-1

RECEIVED

OCT 29 1991

OCS  
HOBBS OFFICE