

DISTRICT I
1625 N. French Dr., Hobbs, NM 88240
DISTRICT II
811 South First, Artesia NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410
DISTRICT IV
2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02069
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1519
7. Lease Name or Unit Agreement Name State J
8. Well No. 4
9. Pool name or Wildcat Vacuum; Grayburg-San Andres
10. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil <input type="checkbox"/> Gas <input type="checkbox"/> Other Injector	
2. Name of Operator Exxon Mobil Corporation	
3. Address of Operator P.O. Box 4358 Houston TX 77210-4358	
4. Well Location Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line Section 22 Township 17S Range 34E NMPH Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG & ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
MULTIPLE COMPLETION <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	OTHER: Temporarily Plug & Abandon <input checked="" type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. (For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion)

01/11/01 to 01/14/01

1. Move in and rig up well service unit.
2. Checked H2S monitor.
3. Unflanged wellhead and nipped up BOP. Tested BOP. Tested OK.
4. Unset packer and pull out of hole with 135 joints tubing and packer.
5. Rig up wireline unit. Run in hole with gauge ring to 3961'.
6. Run in hole with CIBP and set at 3975' with 25' of cement on top of plug.
7. Rig down wireline unit. Rig up pump truck and loaded and tested casing. Tested OK.
8. Run in hole with 1000' of kill string.
9. Run in hole with remaining tubing.
10. Removed BOP. Flanged up wellhead for 30 minutes, tested OK.
11. Circulate packer fluid. Rig down.

This Approval of Temporary
Abandonment Expires 10/28/07

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tiffany A. Stebbins TITLE **Staff Administrative Assistant** DATE **01/11/2002**
TYPE OR PRINT NAME **Tiffany A. Stebbins** TELEPHONE NO. **(713) 431-1207**

(This space for State Use)

APPROVED BY CARY W. WINK DATE **OCT 28 2002**
CONDITIONS OF APPROVAL IF ANY: COC FIELD REPRESENTATIVE H/STATE MANAGER

