

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. NA
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1520
7. Lease Name or Unit Agreement Name BRIDGES STATE
8. Well No. 18
9. Pool name or Wildcat VACUUM GRAYBURG/SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.) NA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Mobil Producing Tx. & N.M. Inc.*

3. Address of Operator *Mobil Exploration & Producing U.S. Inc., as Agent for
Mobil Producing TX. & N.M. Inc., P. O. Box 633, Midland, TX 79702

4. Well Location
Unit Letter F : 1980 Feet From The NORTH Line and 1980 Feet From The WEST Line

Section 24

Township 17S

Range 34E

NMPM LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

NA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU MAYO PARRS. ND WH. NU BOP. MI WS.
2. RIH W/CSG & JACKETS. CUT & PULL
3. RU CMT SERV. RIH/WS TO TOP OF CIBP @ 4204. CIRCL HOLE W/BRINE WTR. SPOT 6 SX CMT (ET FT) ON TOP OF CIBP. PU WS TO 2550.
4. SPOT STUB PLUG W/36 SX CMT 2550-2430. PU TBG TO 1750.
5. SPOT PLUG OF 47 SX CMT 1750-1633 ACROSS TOP OF 1700. TAG CMT PLUG TOP @ 1633. PU TBG TO 867.
6. SPOT PLUG OF 46 SX CMT 867-756. PU TBG TO 50 T.
7. SPOT 21 SX FROM TP-SURFACE. POH W/WS. WOC.
8. ND BOP. RD PU. CUT CSG 3 FT BELOW GD LEVEL. WELL STEEL PLATE ON CSG STUB. ERECT P&A MARKER W/ WELL NAME AND PLUGGED DATE. FILL CELLAR AND CLEAN SURFACE LOCATION.

VERBAL APPROVAL FROM EDDIE SEAY W/NMOCD 6/12/91.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. W. Dixon TITLE Engineering Technician

DATE 7/18/91

TYPE OR PRINT NAME J. W. DIXON

(915)

TELEPHONE NO. 688-2452

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY _____ TITLE _____

DATE

CONDITIONS OF APPROVAL, IF ANY: