Submit to Appropriate District Office State Lease - 6 copies Fee Lease - 5 copies <u>DISTRICT I</u> P.O. Box 1980, Hobbe, N <u>DISTRICT II</u> P.O. Drawer DD, Artesia, DISTRICT III	OIL M 88240	State of New M Minerals and Natural R CONSERVATI(P.O. Box 20 Santa Fe, New Mexico	esources Department	30-02 5. ladicate	5-02091 Type of Lease S	TATE X FEE
1000 Rio Brazos Rd., Azt	oc, NM 87410			6. State Or	l & Gas Lesse	No.
	TION FOR PERMIT	TO DRILL, DEEPEN, O	OR PLUG BACK	<i>\//////</i>		
Ia. Type of Work: DRII b. Type of Well: OIL OAS WELL X WELL [L RE-ENTER	DEEPEN X SINGLE ZONE	PLUG BACK		ame or Unit A ges-Stat	greement Name e
2. Name of Operator Mobil Producing	TX. & N.M. Inc.*			8. Well No 22		
3. Address of Operator *	Mobil Exploration &	Producing U.S. Inc., . O. Box 633, Midlan	as Agent for		ne or Wildcat 100 - Glev	
4. Well Location Unit Letter		rom The South	Line and			East West Line
Section 24	Town	hip 17S Ra	34E	NMPM I	Lea	County
		10. Proposed Depth		<u> Commetice</u>		12. Rotary or C.T.
		TD 6300		Glorietta	1	Rotary
13. Elevations (Show wheth	er DF, RT, GR, etc.)	4. Kind & Status Plug. Bond	15. Drilling Contractor	- <u></u>		Date Work will start
GL 4016	<u>l</u>	On File Unknown		11-06-92		06-92
SIZE OF HOLE		OPOSED CASING AN		T		·····
	SIZE OF CASING	WEIGHT PER FOOT	SETTING DEPTH	SACKS OF CEMENT		EST. TOP
8-3/4	7	24.	<u>781</u> 4278	220 5		Circ.
	Original	Casing Undistur		<u>220 s</u>	X	<u> </u>
6-1/4	4-1/2 10.5 TOL 3900 425 Sx Cl C (Sqz TOL w/400 SX Cl C if necessary)					
Well current Procedure an	ly in San Andre d proposed well	s Zone. Drill d bore sketch atta	eeper request t ched.	o Glorie	tta Forn	mation.
IN ABOVE SPACE DESCRIBE PROPOSED PROGRAM: IF PROPOSAL IS TO DEEPEN OR FLUG BACK, GIVE DATA ON PRESENT PRODUCTIVE ZONE AND PROPOSED NEW PRODUCTIVE ZONE. GIVE BLOWOUT PREVENTER PROGRAM, IF ANY. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SHONATURE						
TYPE OR PRINT NAME	Kaye Políock				710 3	(915) рянома мо. 688-2584
					1042	

(This space for State Use)	<u> </u>	······································	
-	Orig. Signed by Paul Kauta		MARK 0 5 100
APPROVED BY	Geologist	m	DATE

It successfully completed in Herata must go into Texacotinit

Submit to Appropriate District Office State Lease - 4 copies Fee Lease - 3 copies

DISTRICT | P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-102 Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL LOCATION AND ACREAGE DEDICATION PLAT

All Distances must be f	rom the outer boundaries	of the section

Operator				Lease				Well No.
	CING TX & NM I	VC.*, BOX 633	MIDLAND	BRIDGES	STATE			22
Unit Letter	Section	Township		Range			County	
N	24	17-5	<u>}</u>		34E	NMP	м	LEA
Actual Footage Loc	ation of Well:							est-
660 Ground level Elev.	feet from the	SOUTH	line and		*** 195	C feet fro	m the E#	ST line
	Producin	g Formation		Pool	91	-		Dedicated Acreage: 40
4016	e the acreage dedicated	GLORIETTA		VACUUM	- than	ula		SISTISS Acres
2. If more	e than one lease is ded	icated to the well, out	line each and	identify the o	wnership there	of (both as to wor		
3. If more	than one lease of diff	ferent ownership is de	dicated to the	well, have the	interest of al	l owners been cons	olidated by cor	nmunitization,
	tion, force-pooling, etc Yes		er is "ves" tur	e of consolidat				
If answer	is "no" list the owner	and tract description	s which have	actually been of	consolidated.	(Use reverse side a	4	
uns Iom	1 Deccessary.							
No aliowi or until a	able will be assigned to non-standard unit, elin	o the well until all interest,	erests have be has been app	en consolidate roved by the E	d (by commu Division.	nitization, unitizatio	on, forced-pool	ing, or otherwise)
[1	17S 34E			1		OPERA	TOR CERTIFICATION
	i	175 34E					I hereby	, certify that the information
					1		contained her	ein in true and complete to the
	i				1		Desi of my know	wledge and belief.
	1						Signature	- <u>A</u>
	i i				1		Kart	Hallont
					ļ		Printed Name	1 march
	· /						KAYE POLL	OCK
	ļ				-		Position	
	ļ				ł		REGULATO	RY TECHNICIAN
							Company	
	I	1			!			P US AS AGENT-MPTM
	1						Date	
	ł	24			l			10-30-92
	1							
		<u> </u>					SURVEY	OR CERTIFICATION
	i i						l harabu aantii	fy that the well location shown
	i						mereby certig on this plat w	vas plotted from field notes of
	i						ictual surveys	mode by me or under my
	i						nipervison, an	d that the same is true and
	1							e best of my knowledge and
	ł					{	velief.	
				1			Date Surveyed	
				·		╺━━━┝╽		
							Signature & Se Professional Su	al of
10								
	2	2 660'						
	!	1						
	099	1 I					Certificate No.	
	°	<u>'</u>		1			Lenuncatie NO.	
330 660 9	90 1320 1650 1	1980 2310 2640	2000	1500	1000	500 0		

DRILL DEEPER AND SURVEY PROCEDURE

MIRU pulling unit with pumps, mud system, and power swivel. ND WH and NU BOP.

TIH with a 6-1/4" mill tooth journal-bearing bit, casing scraper f/ 7" 24# casing, (2) 4-3/4" (54 lb/ft) DC, and 2-7/8", 10.4#, grade E, AOH DP to 4,310'. POH w/ DP, DC, casing scraper, and bit.

PU a packer and RBP for 7" 24# casing. TIH to 4,300' & set RBP. PU to 200' and set packer. Pressure test RBP to 1500#. Shut-in backside and pressure test casing to 1500# for 30 minutes. If casing holds pressure, go to step #6.

Continue testing up the hole until the casing leak is isolated. Establish an injection rate and pressure for the leak. Contact E. L. Cash @ (915) 688-1404 for a squeeze procedure.

WOC 24 hrs. TIH with a 6-1/4" mill tooth bit w/ (15) 4-3/4" DC, and 2-7/8" DP. DO all cement plugs. Shut-in backside and test casing to 1500# for 30 minutes. Clean out hole to top of RBP. Wash all sand off RBP. POH w/ DP, DC, and bit. PU retrieving head and DP.

TIH to the RBP. Retrieve the RBP and POH w/ DP, packer, retrieving head, and RBP.

TIH with a 6-1/4" mill tooth journal-bearing bit, (15) 4-3/4" DC, and 2-7/8", 10.4#, grade E, AOH DP. Clean out open-hole from 4,278' to TD at 4,700'. Drill 10' of new formation.

POH with 6-1/4" bit. DC, and DP. TIH w/ 6-1/4" Smith F-4 insert bit w/ (15) 4-3/4" DC, and 2-7/8" DP.

Drill to TD @ 6,300'. Run TOTCO surveys every 500' while drilling new formation.

CEMENTING PROCEDURE

Two pump trucks with recirculating type mixers will be required. One pump truck will be used as a standby only. Use a pressurized mud balance to check the cement density. Record the following job parameters versus time: pump rate, pump pressures, fluid density and total volumes pumped. Collect cement samples per procedure in appendix.

Reciprocate the liner 10' - 15' (2-3 minutes per stroke). Reciprocate while conditioning the hole, mixing cement and displacing cement. If surge and swab pressures are excessive, discontinue reciprocation. Circulate at least one hole volume prior to cementing.

Pressure test lines to 3000 psi for 5 minutes, prior to cementing.

Preceed cement with 25 bbls of fresh water.

Pump cement downhole at 4 bpm.

Displace cement with 55 bbls of fresh water. DO NOT OVER-DISPLACE.

Release liner. POOH with running tool and lay down drillpipe.

WOC 24 hrs. TIH w/ 7" packer. Test TOL to 500# for 30 minutes. If TOL holds, turn well over to production. If TOL leaks, contact E. L. Cash @ (915) 688-1404 for a liner top squares $=10^{-11}$

ł



BRIDGES STATE #22 LEA COUNTY, NEW MEXICO PROPOSED WELLBORE SKETCH

