

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-02098

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.
NA

7. Lease Name or Unit Agreement Name

STATE G

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER Injection

2. Name of Operator

Mobil Producing Tx. & N.M. Inc.*

3. Address of Operator

*Mobil Exploration & Producing U.S. Inc., as Agent for
Mobil Producing TX. & N.M. Inc., P. O. Box 633, Midland, TX 79702

8. Well No.

3

9. Pool name or Wildcat

VACUUM (GRAYBURG/SAN ANDRES)

4. Well Location

Unit Letter G : 1980 Feet From The NORTH Line and 1980 Feet From The EAST Line

Section 24

Township 17S

Range 34E

NMPM LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

NA

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/12/91 - MIRU MAYO MARRS UNIT.

9/13/91 - BROKE OUT WELLHEAD. NU BOP. RIH W/TBG TO CIBP 4230. DISPLACED 7 CSG W/130 BBLS 10# BRINE WATER. POH & STOOD BACK 2300' OF TBG AND LD REST. SDFN & WEEK-END.

9/16/91 - ND BOP. DUG OUT CELLAR. BROKE OUT SURFACE HEAD. CUT 7 CSG 2305. PUMPED CSG TO 730#

PRESS UP DID NOT CIRC. CONSULTED W/R. SMITH-NMOCD-HOBBS. PERMISSION TO SET 100' PLUG ACROSS CSG CUT - 2360 TO 2160. POH W/1600' OF TB & LD REST. CUT CSG AT 1595 - AS PER JACK GRIFFIN NMOCD-HOBBS. CSG STILL STUCK.

9/17-18/91 - POH W/ WS. LD 500' & STOOD BACK 15 STDS. RIH & TAG CMT PLUG AT 1506. POH. RIH TO 900 TO 900'. CO CELLAR, PU CSG HEAD & RU CSG TOOLS. PU CSG & CUT TOP JTS LOOSE. FIN POH W/CSG.

9/19/91 - MIX & PUMP 70 SX C FOR STUB & SURF SHOE PLUG. POH LD WS. SD WOC.

9/20/91 - RIH TAG TOP OF CMT PLUG 714. POH. MIX & PUMP 21 SX C. SPOTTED SURF PLUG F/50'-SURF. POH & LD 2 JTS. CLEANRED OUT CELL & 2' INSIDE CSG. CMT WAS IN CELLAR. RDMO MAYO PU WELL P&A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J. W. Dixon

TITLE

Engineering Technician

DATE 9/23/91

(915)

TYPE OR PRINT NAME

J. W. DIXON

TELEPHONE NO. 688-2452

(This space for State Use)

APPROVED BY

Carly M. Lief

TITLE

DATE

9/23/91

CONDITIONS OF APPROVAL IF ANY:

B R N

8