

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-02100

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-1520

SEVERAL NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐

GAS WELL ☐

OTHER

2. Name of Operator

Texaco Exploration & Production Inc.

3. Address of Operator

205 East Broadway Hobbs, NM 88240

4. Well Location

7. Lease Name or Unit Agreement Name

Mobile Bridges State  
Vacuum Blinbrey

8. Well No.

11

9. Pool name or Wildcat

Vacuum Blinbrey

Unit Letter F : 1980 Feet From The FNL Line and 1978 Feet From The FWL Line

Section

5

Township

17-S Range 34-E

NMPM

LEA

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 110.

1. Cut window in 7" @1063, Drill cmt down to 1722

2. 2/10/98 Mix & pump 25 sx cmt from 6006 to 5628

3. 2/10/98 Mix & pump 25 sx cmt from 5604 to 4626

4. 2/10/98 Mix & pump 25 sx cmt from 4250 to 3916

5. 2/10/98 Mix & pump 25 sx cmt from 2970 to 2800

6. 2/11/98 Perf 4 holes @ 1740, mix & pump 50 sx cmt, pressure up to 1000 psi, tag @ 906

7. 2/11/98 Mix & pump 25 sx cmt from 906 to 620

8. 2/11/98 Mix & pump 30 sx cmt from 407 to 0

9. 2/16/98 Cut off wellhead, built dry hole marker, cut anchors, covered, cleaned location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wayne Brooks TITLE \_\_\_\_\_ DATE 2-24-95

TYPE OR PRINT NAME Wayne Brooks 915-683-5321 TELEPHONE NO. \_\_\_\_\_

(This space for State Use) ORIGINAL SIGNED BY

ARY WINK

APPROVED BY FELD REE

TITLE \_\_\_\_\_ DATE 9-7-99

CONDITIONS OF APPROVAL, IF ANY: