

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-02112

5. Indicate Type of Lease

STATE ☒ FEE

6. State Oil / Gas Lease No.

B- 1056

7. Lease Name or Unit Agreement Name

CENTRAL VACUUM UNIT

8. Well No.

37

9. Pool Name or Wildcat

VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER ☐

2. Name of Operator

TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator

205 E. Bender, HOBBS, NM 88240

4. Well Location

Unit Letter O : 660 Feet From The SOUTH Line and 1980 Feet From The EAST Line

Section 25 Township 17S Range 34E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT,GR, etc.)

3997' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☒

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPERATION ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

REPAIR CSG LEAK ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/08/00: MIRU. NDWH. NUBOP. TIH W/KILL STRING TO 1300'.

6-09-00: TIH W/BIT, CSDG SCRAPER, TBG TO 4092'. TIH W/RBP/PKR, WS. SET RBP @ 3939'. PULL PKR TO 3874'.

6/12/00: DISPL W/FW. SET PKR @ 3874'. TEST RBP TO 1000 PSI-OK. ISOLATE CSG LEAK 2775-2837. SWAB DRY.

6/13/00: FL @ 500'. REL PKR. TIH W/TBG OPEN ENDED TO 2861'. SPOT 25 SX SQUEEZECRETE 2861-2602'.

6/16/00: TIH W/BIT, DC'S & TBG. TAG @ 2601'. DRILL 302'CMT TO 2903'. RAN BIT TO 2945'. TEST CSG TO 500 PSI.

6/19/00: TIH W/RETR TOOL. TAG UP @ 3850'. WASH SAND OFF RBP @ 3874'. FISH RBP @ 3874'. TIH W/BIT, DC'S & TBG TO 2000'.

6/21/00: TAG @ 4726'. C/O 4726-4736. TIH W/PKR & SET @ 3938. TEST CSG TO 500-OK.

6/22/00: ACIDIZE WS/6000 GALS 15% NEFE HCL ACID. END FL @ 1200.

6/23/00: REL PKR. TIH W/BIT, DC'S & TBG. TAG @ 4736'. TIH TO 3708'.

6/26/00: KILL W/10# BRINE. TIH W/MOTOR, SEAL, GAS SEPR, PUMP, TBG. NDBOP. NUWH. QCI WH.

6/27/00: BUILD WH. SPLICE QCI CONNECTION. WELL PUMP UP @ 10:30 AM. RIG DOWN.

7/13/00: ON 24 HR OPT. PUMPING 17 BO, 834 BW, & 9 MCF. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE

J. Denise Leake

TITLE

Engineering Assistant

DATE 8/22/00

TYPE OR PRINT NAME

J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL IF ANY:

TITLE

DATE