

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-02137

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
B-1030

7. Lease Name or Unit Agreement Name
WEST VACUUM UNIT

8. Well No.
5

9. Pool name or Wildcat
VACUUM GRAYBURG SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER INJECTION WELL

2. Name of Operator
Texaco Exploration and Production Inc.

3. Address of Operator
P. O. Box 730 Hobbs, NM 88240

4. Well Location
Unit Letter M : 660 Feet From The SOUTH Line and 660 Feet From The WEST Line
County
Section 28 Township 17-S Range 34-E NMPM LEA

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4069' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING
OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
CASING TEST AND CEMENT JOB
OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1. MIRU, INSTALL BOP, TIH W/ BIT ON 2 7/8" WS & C/O TO 4435' (PBDT), TOH.
- 2. RUN CBL TO FIND TOP OF CMT OUTSIDE 5 1/2" CSG. LOAD HOLE W/ SALT GEL MUD.
- 3. IF TOC IS BELOW 2690' THEN GO TO STEP #4. IF TOP IS ABOVE 2690' THEN BY WIRELINE SET CIBP @ 2725' & CAP W/ 35' CMT. GO TO STEP #5.
- 4. PERFORM 2 SQZ HOLES @ 2790'. RIH W/ CMT RET & WS TO 2690', EST CIRC INTO SQZ PERFS. SQZ W/ 50 SX CMT. FLUSH TBG W/ 14 BBLs, PULL OUT OF RET & FLUSH REMAINING CMT TO CAP RET.
- 5. SET CIBP @ 1658', CAP W/ 35' CMT.
- 6. TIE ONTO CSG & EST CIRC TO SURF THROUGH CSG LEAK (683'-1637"). SQZ CMT UNTIL CIRC TO SURF. SI ANNULUS & SQZ AN ADDL 200 SX CMT. TOTAL CMT APPROX 460 SX.
- 7. CUT OFF WELLHEAD, INSTALL MARKER, CLEAN LOCATION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE ENGINEER'S ASSISTANT DATE 10-1-92

TYPE OR PRINT NAME MONTE C. DUNCAN TELEPHONE NO. 393-7191

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEKIDOM
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE OCT 07 1992

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
OCT 06 1992
SOD HOBBS 221