

## **MISCELLANEOUS NOTICES**

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

		Indicate Nature	of Notice by Cl	ecking Belo	W		
Notice of Intention to Change Plans		Notice of Inten Temporarily Ab			Notice of Intention to Drill I)eeper		
Notice of Intention to Plug Well	I	Notice of Intento Plug Back	ITION		Notice of Intention to Set Liner		<u>-</u>
Notice of Intention to Squeeze		Notice of Inten to Acidize	NTION		Notice of Intention to Shoot (Nitro)		
Notice of Intention o Gun Perforate		Notice of Inten (Other)	NTION		Notice of Intention (Other)	г	
OIL CONSERVATION CONSANTA FE, NEW MEXICO	Eunice, New Mexico			January 15, 1957			
Gentlemen:			(Flace)		(	(Date)	
Following is a Notice of	Intention to do c	ertain work as de	escribed below a	the			
eville G. Penro	se, Inc.	Ph <b>i</b>	llips Lea	<b>1</b>	.Well No3	in	J
(Com  1/4 SE 1/4 O  (40-acre Subdivision)	pany or Operator)  f Sec. 31	T. <b>17</b> S	R 34E	NMPM	Vacuum		(Unit)
Lea	Count	t-17					
ropose the foll un 10 sack ceme	FULL (FOLLOW I owing pla nt plug a	DETAILS OF INSTRUCTIONS In to plug	and abai	es and r	egulations) is well:		
ropose the foll un 10 sack ceme un 15 sack ceme un 15 sack ceme un 5 sack cemen	FULL (FOLLOW I  owing pla  nt plug a  nt plug i  nt plug i  t plug at	DETAILS OF INSTRUCTIONS In to plug It TD of 4 In and out In and out	and abar 7521. of 7" ca of 8-5/8	es and R ndon th asing s	is well: tub. ng at 1570.	an <b>up</b> .	
Propose the follown 10 sack ceme tun 15 sack ceme tun 15 sack cementun 5 sack cementur 5 sack cementur 4 18 pip	FULL (FOLLOW I  owing pla  nt plug a  nt plug i  nt plug i  t plug at	DETAILS OF NSTRUCTIONS In to plug it TD of 4 in and out in and out surface. properly	and abar 7521. of 7" ca of 8-5/8	es and R ndon th asing s	is well: tub. ng at 1570.	se, Inc.	Bui sh
Propose the follown 10 sack ceme on 15 sack ceme on 5 sack cemen or 4 18 pip	FULL (FOLLOW I owing plant plug ant plug i t plug at e marker	DETAILS OF NSTRUCTIONS In to plug it TD of 4 in and out in and out surface. properly	and abar 752 of 7 ca of 8-5/8 inscribed	Nevi	is well:  tub.  ng at 1570.  location cle	se, Inc.	Bright
Propose the foll In 10 sack ceme In 15 sack ceme In 15 sack ceme In 5 sack cemen In 5 sack cemen In 6 propose In 6 propose In 6 propose In 6 propose In 7 propose In 7 propose In 8 propose	FULL (FOLLOW I)  owing plant plug and plug int plug at the plug at	DETAILS OF NSTRUCTIONS In to plug it TD of 4 in and out in and out surface. properly	and abar 7521. of 7" ca of 8-5/8	Nevi	is well:  tub.  ng at 1570.  location cle	se, Inc. T.H.	Bright
Propose the foll dun 10 sack ceme dun 15 sack ceme dun 15 sack cemen dun 5 sack cemen derrect 4*18° pip	FULL (FOLLOW I)  owing plant plug and plug int plug at the plug at	DETAILS OF NSTRUCTIONS In to plug it TD of 4 in and out in and out surface. properly	and abar 7521. of 7" ca of 8-5/8 inscribed	Nevi Prod	is well:  tub.  ng at 1570.  location cle	T.H.	Bright