Submit 3 Copies To Appropriate District Office		State of New Mexico			Form C-103	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			WELL ADINO	Revised March 25, 1999 WELL API NO.	
District II	OII COMPRESSION PRINCIPAL			30-025-02181	<b>'.</b>	
1301 W. Grand Ave., Artesia, NM 88210 District III				5. Indicate Typ	1	
1000 Rio Brazos Rd., Aztec, NM 87410  District IV  Santa Fe, NM 87505				STATE X FEE   6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505				6. State Oil & 858150	CGas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name	7. Lease Name or Unit Agreement Name:	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				West Vacuum I	West Vacuum Unit	
Type of Well:     Oil Well X Gas Well  Other						
2. Name of Operator				8. Well No.	8. Well No.	
Chevron Texaco Corporation				8	<u> </u>	
3. Address of Operator P.O. Box 3109 Midland, Texas 79702					Pool name or Wildcat     Vacuum Grayburg San Andres	
4. Well Location				vacuum Graybi	urg San Andres	
Unit Letter B: 990 feet from the North line and 2310 feet from the East line						
Section 33	Township 1	7S	Range 34E	NMPM	Lea County	
	10. Elevation (Show w	hether D		R, etc.)		
11 Check Appropriate Poy to Indicate Nature of Notice Person of Notice Per						
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL W		ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE	DRILLING OPNS.	PLUG AND X	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TES		ABANDONMENT	
OTHER:					_	
	d operations (Clearly stat	a all parti	OTHER:	d airea maria mat dutam		
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.						
1. RIH Tag CIBP @ 4145 spot 50 sxs. Plug 4145 to 3800 (Grayburg San Andres Queen) Tag @ 3789						
2. Displace hole w/MLF, 9.5# Brine w.25# gel P/BBL						
3. Spot 90 sxs. Plug 2800 to 2300 (Yates, B-Salt, csg. @ 2355 to 2616) Tag @ 2315 (Okayed w/OCD)						
4. Perf 6 hole @ 1400, sqz. 75 sxs. 1400 to 1200 (T-Salt) Tag @ 1128					1. 18 j	
5. Perf 6 hole @ 400 sqz. 100 sxs 400 to 150 (10" shoe) Tag @ 112  Approved as to plugging of the Well Bore.						
6. CIRC cmt. 30 to surf. w/15 sxs., install dry hole marker 1/21/02  Liability under bond is retained until surface restoration is completed.						
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE SIGNATURE			NANAGER		DATE 1/21/02	
Type or print name Jumpy	BAGLEY			Tal-	phone No. 915 683-4996	
(This space for State use)						
APPPROVED BY Yangle	Jillimbe TI	ITLE			DATEN 2 1 2002	
Conditions of approval, if any: WWINK GARY: WWINK OPE FIELD REPRESENTATIVE II/STAFF MANAGER						
OPFIELD RI	EPRESENTATIVE II/STAFI	WAN	<i>&gt;</i> 2.76			

ر ت ع

SANT OF WHAT WENT ONE OF THE WASHEST