

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-02181
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Texaco Exploration & Production, Inc.		6. State Oil & Gas Lease No. 858150
3. Address of Operator P. O. Box 3109, Midland, TX 79702		7. Lease Name or Unit Agreement Name: West Vacuum Unit
4. Well Location Unit Letter <u>B</u> : <u>990</u> feet from the <u>North</u> line and <u>2310</u> feet from the <u>East</u> line Section <u>33</u> Township <u>17S</u> Range <u>34E</u> NMPM Lea County		8. Well No. 8
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Vacuum, Grayburg, San Andres

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

- 12. Describe proposed or completed operations.** (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
1. RIH Tag TOC on CIBP +- 4145', spot 50 Sx plug 4145'-3800'. (Grayburg San Andres, Queen) WOC Tag.
 2. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL.
 3. Spot 90 Sx plug 2800'-2300', (Yates, B-Salt, Csg leaks 2355'-2616') WOC Tag.
 4. Perf 6 holes @ 1400', Sqz 75 Sx plug 1400'-1200' (T-Salt) WOC Tag.
 5. Perf 6 holes @ 400', Sqz 100 Sx plug 400'-150' (10" shoe) WOC Tag.
 6. 10 Sx surface, Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James T. Corbett TITLE FACILITY ENGR

Type or print name JAMES T. CORBITT
(This space for State use)

DATE 11/5/01

Telephone No. 688-4438

APPROVED BY _____ TITLE _____

Conditions of approval, if any:

DATE _____

JP