

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-1576	
7. Unit Agreement Name	
West Vacuum Unit	
8. Farm or Lease Name	
West Vacuum Unit	
9. Well No.	
9	
10. Field and Pool, or Wildcat	
Vacuum Grayburg	
an Andres	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER- Water Injection

2. Name of Operator
TEXACO Inc.

3. Address of Operator
P. O. Box 728, Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER A 990 FEET FROM THE North LINE AND 990 FEET FROM
THE East LINE, SECTION 33 TOWNSHIP 17-S RANGE 34-E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)
4062' (GR)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER ADDL PERFS IN GRAYBURG ZONE <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

1. RIG UP. INSTALL BOP. PULL INJECTION TUBING AND PACKER.
2. CLEAN OUT TO 4710' (TD).
3. PERFORATE 7" CASING W/ 2-JSPF @ 4230', 42', 76', 83', 91', 95', 4443', 4505', 16', 28', 31', AND 4536'.
4. SET PKR. @ 4550'. ACIDIZE PERFS 4602' - 4710' W/ 1500 GALS STABILIZED GELLED 15% HCL ACID.
5. SET RBP @ 4550' AND PKR @ 4200'. ACIDIZE PREFS 4230' - 4536' W/ 3000 GALS STABILIZED GELLED 15% NE HCL ACID IN 2-STAGES USING 300# ROCK SALT BETWEEN STAGES. PULL RBP.
6. INSTALL INJECTION EQUIPMENT. RETURN TO INJECTION.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Asst Dist Mgr DATE 8-22-83

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT 1 SUPERVISOR TITLE DATE
CONDITIONS OF APPROVAL, IF ANY

AUG 24 1983

RECEIVED

AUG 23 1983

O.C.D.
HOBBBS OFFICE