

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		<b>WELL API NO.</b> 30-025-02195
<b>1. Type of Well:</b> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Injector <input type="checkbox"/>		<b>5. Indicate Type of Lease</b> STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
<b>2. Name of Operator</b> Texaco Exploration & Production, Inc.		<b>6. State Oil &amp; Gas Lease No.</b> B-871
<b>3. Address of Operator</b> P. O. Box 3109, Midland, TX 79702		<b>7. Lease Name or Unit Agreement Name:</b> West Vacuum Unit
<b>4. Well Location</b> Unit Letter <u>M</u> : 660 feet from the <u>South</u> line and 660 feet from the <u>West</u> line Section <u>33</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>Lea</u> County		<b>8. Well No.</b> #30
<b>10. Elevation (Show whether DR, RKB, RT, GR, etc.)</b>		<b>9. Pool name or Wildcat Vacuum</b> Grayburg, San Andres

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- Set 5 1/2" CIBP @ 4325' (Grayburg-San Andres) Spot 25 Sx plug 4325'-4100' Tag 4085'
- Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL
- Spot 25 Sx plug 3800'-3600' (Queen)
- Spot 25 Sx plug 2800'-2600' (Yates, B-Salt) Tag @ 2580'
- Spot 25 Sx plug 1800'-1600' (T-Salt) Tag @ 1595'
- Perf 6 holes @ 950', Sqz w/125 Sx 950'-700' (8 5/8" shoe) Tag @ 742' Re-Spot 25 Sx plug 742'-500' Tag @ 467'
- Circ Cmt 30' to Surf w/10 Sx. Install dry hole marker. 9/17/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 9/17/01

Type or print name Jimmy BAGLEY Telephone No. 915 683-4996  
(This space for State use)

APPROVED BY Johnny Robinson TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
Conditions of approval, if any:

GWV