

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-02198
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1406-1
7. Lease Name or Unit Agreement Name WEST VACUUM UNIT
8. Well No. 12
9. Pool name or Wildcat VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4031' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Texaco Exploration and Production Inc.	3. Address of Operator P. O. Box 730 Hobbs, NM 88240	4. Well Location Unit Letter B : 330 Feet From The NORTH Line and 1650 Feet From The EAST Line Section 34 Township 17-S Range 34-E NMPM LEA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4031' GR			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 2/9/93 - 2/13/93
- MIRU, TOH W/ PROD EQUIP. TAGGED TD @ 4635'.
 - SPTD 325 GALS AMMONIUM BICARBONATE FR 4635'-4238', SET PKR @ 3800', SQZD 325 GALS AMMONIUM BICARBONATE INTO FORMATION, SION.
 - SPTD 325 GALS 15% HCL NEFE FR 4635'-4283', SET PKR @ 3800', SQZD AN ADDL 325 GALS. SI 1 HR, SWABBED BACK LOAD.
 - ACIDIZED OH FR 4635'-4283' W/ 6000 GALS 15% HCL NEFE. MAX P = 3300#, AIR = 4 BPM.
 - SCALE SQZD W/ 1 DRUM TH-793 IN 12 BFW, OVERFLUSHED W/ 150 BFW.
 - RETURNED WELL TO PRODUCTION.
OPT 2/26/93 16 BOPD, 55 BWPD, 1 MCFD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE ENGINEER'S ASSISTANT DATE 4-5-93
TYPE OR PRINT NAME MONTE C. DUNCAN TELEPHONE NO. 393-7191

(This space for State Use) Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE APR 08 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

APR 04 1993

OCD HOBBS OFFICE