

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 02208
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-871
7. Lease Name or Unit Agreement Name	WEST VACUUM UNIT
8. Well No.	35
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	4041' DF

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	P.O. BOX 730, HOBBS, NM 88240
4. Well Location	Unit Letter <u>N</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>WEST</u> Line Section <u>34</u> Township <u>17S</u> Range <u>34E</u> NMPM <u>LEA</u> COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: REQUEST TEMPORARILY ABANDONMENT STATUS <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1/20/94 - 1/21/94

1. NOTIFIED NMOCD. TOH W/ PRODUCTION EQUIPMENT.
2. SET CIBP @ 4105' & CAPPED W/ 35' CMT, PBTD @ 4070'.
3. CIRCD HOLE W/ INHIBITED FLUID & TSTD AS PER NMOCD GUIDELINES TO 520# FOR 30 MIN, HELD OK.
4. TOH W/ TBG. REQUEST TEMPORARILY ABANDON WELL STATUS THROUGH 2/1/99.

(ORIGINAL CHART ATTACHED, COPY OF CHART ON BACK)

This Approval of Temporary
Abandonment Expires 2-1-99

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Monte C. Duncan TITLE Engr Asst DATE 2/16/94

TYPE OR PRINT NAME Monte C. Duncan Telephone No. 397-0418

ORIGINAL SIGNED BY JERRY SEXTON

(This space for State Use)

DISTRICT I SUPERVISOR

APPROVED BY Jerry Sexton TITLE District I Supervisor DATE FEB 21 1994

CONDITIONS OF APPROVAL, IF ANY:

JCS
JLC
do

PRINTED IN U.S.A.

DAY

NIGHT

TEXACO E&P
INSTRUMENT ENGINEERS

WVU # 35 L.D.
CIBP 4135 @ 4145
FOTO C 4070

DATE WORKED	DATE TAKEN UP
DATE PUT IN	DATE TAKEN OFF
DATE PUT IN	DATE TAKEN OFF

BR-2221
B 0-1000-S
1/20/93 B.H.

TEXACO EXPLORATION AND PRODUCTION INC
PO BOX 730
HOBBS NEW MEXICO 88241-0730
Gen. B. J. FODDERS A-3725
Per. C. 00571 New 1/20/93
3082-025-02150
A-1