

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-02209

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

858150

7. Lease Name or Unit Agreement Name:

West Vacuum Unit

8. Well No.

26

9. Pool name or Wildcat

Vacuum, Grayburg S.A.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Chevron USA, Inc.

3. Address of Operator

15 Smith Rd. Midland, Tx 79705

4. Well Location

Unit Letter L : 1980 feet from the south line and 660 feet from the west line

Section 34

Township 17-S

Range 34-E

NMPM

County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Tag 5 1/2 CIBP @ 4082 spot 25sx plug fr/4082-3900(Grayburg-San Andres)Tag @ 3869
2. Displace hole w/MLF 9.5# Brine w/25# Gel P/BBL.
3. Spot 25sx plug fr/2700-2500(B-salt)
4. Perf 4 holes @ 1600 sqz w/75sx fr/1600-1500(T-salt) Tag @ 1420
5. Perf 4 holes @ 950 sqz w/75sx fr/950-800(8 5/8 shoe)Tag @ 787
6. Perf 4 holes @ 300 circ cmt 5 1/2 X 8 5/8 w/185sx fr/300-surf Tag @ surf
7. Install dry hole marker 1-28-03

Approved as no plugging of the Well Bore.

Liability under bond is retained until

surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE MANAGER/SUNSET

DATE 1-28-03

Type or print name

Jimmy BAGLEY

Telephone No 915 520-8756

APPROVED BY

ORIGINAL SIGNED BY

GARY W. WINK

OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

FEB 11 2003

Conditions of approval, if any:

typed