

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|                                      |  |
|--------------------------------------|--|
| WELL API NO.                         | 30 025 02209   |
| 5. Indicate Type of Lease            | STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil / Gas Lease No.         | 858150   |
| 7. Lease Name or Unit Agreement Name | WEST VACUUM UNIT   |
| 8. Well No.                          | 26   |
| 9. Pool Name or Wildcat              | VACUUM GRAYBURG SAN ANDRES   |

**SUNDRY NOTICES AND REPORTS ON WELL**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

|  |  |
|--|--|
| 1. Type of Well:                                   | OIL WELL <input checked="" type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>   |
| 2. Name of Operator                                | TEXACO EXPLORATION & PRODUCTION INC  |
| 3. Address of Operator                             | 205 E. Bender, HOBBS, NM 88240   |
| 4. Well Location                                   | Unit Letter <u>L</u> : Feet From The _____ Line and _____ Feet From The _____ Line<br>Section <u>34</u> Township <u>17S</u> Range <u>34E</u> NMPM _____ LEA COUNTY |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) |  |

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up pulling unit. TOH with production equipment
2. TIH with 2 7/8" work string and 5 1/2" Pkr.
3. Set CIBP @ +/- 4120' and dump 35' cmt on top of plug.
4. Circulate hole with inhibited fluid and tested as per NMOCD guidelines to 500# for 30 minutes.
5. Request temporary abandon well status.

THE COMMISSION MUST BE NOTIFIED  
24 HOURS PRIOR TO COMMENCING WORK

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Siamak Safargar TITLE Prod. Engineer

DATE May 6, 97

TYPE OR PRINT NAME M. Siamak Safargar

Telephone No. 397-0429

(This space for State Use)

APPROVED BY Charles L... TITLE OIL & GAS INSPECTOR

DATE 8-1-97

CONDITIONS OF APPROVAL, IF ANY:

