

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	20-025-02217
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name
2. Name of Operator CONOCO INC	8. Well No.
3. Address of Operator 10 West Drive NE 100W, Midland, TX 79705	9. Pool name or Wildcat VACUUM (G-SA)
4. Well Location Unit Letter: _____ : 1980 Feet From The NORTH Line and 1980 Feet From The EAST Line Section 35 Township 17 S Range 34 E NMPM LEA County	10. Elevation (Show whether OF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: TEMPORARY ABANDON <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-27-93 MIRU. POOH W/ RODS, PUMP AND TBG. RIH W/ BIT & SCRAPER TO 4100'. POOH. WIH W/ REP & PKR. REP SET @ 4102'. CIRC PKR FLUID. TEST CSG TO 500# FOR 30 MIN - HELD.
1-29-93 RLMO. CHART ATTACHED.

REQUEST PERMISSION TO TEMPORARY ABANDON THIS WELL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill R. Keathly TITLE SR REGULATORY SPEC. DATE 5-19-93

TYPE OR PRINT NAME BILL R. KEATHLY TELEPHONE NO. 915-686-5424

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 21 1993

CONDITIONS OF APPROVAL, IF ANY:

This Approval of Temporary Abandonment Expires 5-15-98

RECEIVED

MAY 20 1993

OCD HGBBS OFFICE

PRINTED IN U.S.A. 9

10

11

12

1

2

3

4

5

NIGHT

DAY

5

4

3

2

12

11

10

9

8

7

6

5

4

3

2

1

0

900

800

700

600

500

400

300

200

100

0

900

800

700

600

500

400

300

200

100

0

900

800

700

600

500

400

300

200

100

0

TEJAS
INSTRUMENT ENGINEERS


STATE H-35 #5

METER NUMBER
TIME PER DAY
DATE STARTED

WIRE & AMP. SIZE
TIME TAKEN OFF
DATE TAKEN OFF

BR-2221
B 0-1000-S

B.H.H.



DAY

NIGHT

STATE H-35 #5

4-29-93

AA OILFIELD SERVICE
MAC ME WILLIAMS
UNIT #12

60 MIN. CLOCK

~~Plaster e~~
RBP e 4102'

RECEIVED
MAY 20 1993
OCD HOBBS OFFICE