

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
B-3196

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator CONTINENTAL OIL COMPANY	8. Farm or Lease Name STATE H-35
3. Address of Operator P. O. Box 460, Hobbs, N.M. 88240	9. Well No. 5
4. Location of Well UNIT LETTER G 1980 FEET FROM THE NORTH LINE AND 1980 FEET FROM THE EAST LINE, SECTION 35 TOWNSHIP 17-S RANGE 34-E N.M.P.M.	10. Field and Pool, or Willcat VACUUM G-5A
15. Elevation (Show whether DF, RT, GR, etc.) 4023' DF	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to Clean out to TD 4695' & Run GR-SAP Log from TD to 2700' & caliper OH. Acid frac @ 5 BPM: Pump pad of 3,000 gals trtd fresh wtr., 3,000 gals 28% acid. Over flush w/ 1,500 gals gelled trtd fresh wtr. Set Lxner OH BP w/10' sand on top - depth to be determined by logs. Treat w/ Acid frac same as above. Drillout & push OH BP to TD. Re-run prod. Eqpt.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE for Division Office Manager DATE 10-14-74

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

at once - 16 file