

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-025-02219

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-2317

7. Lease Name or Unit Agreement Name
STATE 35 UNIT

8. Well No.
22

9. Pool name or Wildcat
VACUUM GRAYBURG/SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook Street Odessa, TX 79762

4. Well Location
Unit Letter **I** : **1980** Feet From The **FSL** Line and **660** Feet From The **FEL** Line
Section **35** Township **17S** Range **34E** NMPM **LEA** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4013' RKB, 4002' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: **PLUG & ABANDONMENT** ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.


11/18/99 MIRU POOL CO RIG #589 & PLUG EQMT, SI TBG PRESS 500# SI CSG PRESS 500#, BLD PRESS OFF, PMP 10# BRINE STATIC, SECURE, SDON, NO WH NU CLASS II HYDRAULIC BOPE REL TAC TOH W/ 132 JTS 2.875" PROD TBG RU WL & GIH W/7" WL SET CIBP ATTEMPT T/SET 4070' MISRUN POOH CHG OUT FIRING CAP, GIH & SET @ 4070' RD WL, TIH W/25 STDS WS, SECURE.

11/19/99 OBSERVE, STATIC, PU 85 JTS WS 134 JTS TOT TAG CIBP @ 4070' MIX & PMP 150 BBL 10# GELL BRINE, CIRC, PMP PLUG #1 100 SX CL C 14.8 PPG 1.32 CFPS CMT 4070-3470', LD 40 JTS WS T/2817' PMP PLUG #2 25 SX CL C 14.8 PPG 1.32 CFPS 2817-2697', LD 43 JST WS & TOH W/24 STDS, RU WL & PERF 1635' RD WL, BRK CIRC & OBSERVE, STATIC, ESTAB PI 1.75 BPM @ 1100# SI @ 750# PMP PLUG #3 65 SX CL C 14.8 PPG 1.32 CFPS 1635-1500' WOC & TAG, SECURE.

11/20/99 POOH & LD PKR, TAG PLUG #3 1527' MIX & CIRC MUD LD WS RU WL & PERF 200' RD WL TRK, DIG OUT CELLAR PMP PLUG #4 RDMO TEMP DROP F/REPORT

(CONTINUED ON BACK)


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE 
TYPE OR PRINT NAME **Larry M. Sanders**

TITLE **Senior Regulation Analyst** DATE **1-6-00**

TELEPHONE NO. **(915) 368-1488**

(This space for State Use)

APPROVED BY 
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

JA GWW

4/5

STATE 35 UNIT #22

CONTINUED

12/08/99

DIG OUT CELLAR, CUT OFF 13-3/8" WH, 9-5/8" CSG & 7" CSG, WELD ON 14' OFF CONDUCTOR, FILL IN CELLAR
TEMP DROP F/REPORT

01/04/2000

RU POOL T/1" 13-3/8" X 9-5/8" ANNUL, PMP 50 SX CIRC T/SURF RDMO WELL P&A'D
COMPLETE DROP FROM REPORT