ENERGY AND MINERALS DEPARTMENT

MS. OF COPIES RECEIVED		
DISTRIBUTION		
BANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE	Ţ	
OPPRATOR		

OH ONSERVATION DIVISION

		— -I	/	CHOIL DIVISIO	/ I N		
DISTRIBUTIO)H		P. O. BC	X 2088			Form C-103 Revised 10-1-7
BANTA FE			SANTA FE, NEV	V MEXICO 87501			KEA1260 10-1-
FILE						5a. Indicate Typ	e of Lease
U.S.G.S.						i	_
LAND OFFICE		\neg				State XX	Fee
OPERATOR		-				5. State Oil & G	as Lease No.
<u> </u>		 -				В-870	
· · · · · · · · · · · · · · · · · · ·	C1 11 15					mmm	ETTITITI
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)							
1.	WELL	OTHER				7. Unit Agreeme Vacuum Gr San Andre	avburg
2. Name of Operator						6 varumus av	
TEXACO I	nc.					San Andre	
3. Address of Operator						9. Well No.	E OHIO
						66	
	ж 7 28, Н	obbs, New	<u> Mexico 88240</u>			1	
4. Location of Well	ŕ		LET FROM THE South			Vacuum Gr San Andre	ool, or Wildom ayburg S
UNIT LETTER		<u> 1900 - 20</u>	CET FROM THE SOUTH	LINE AND	FEET FROM	mmm	mmm
	•						
THE West	LINE, SEC	т 10N <u>35</u>	TOWNSHIP17	<u>-S</u> RANGE <u>34-</u> F	NMPM.		
		1/////	5. Elevation (Show whethe	r DF, RT, GR, etc.)		12. County	
			4026' (DF)		Lea	
16.	~~~~~						
	Check	c Appropriat	te Box To Indicate I	Nature of Notice, R	eport or Oth	ier Data	
N	OTICE OF	INTENTION	TO:	s	UBSEQUENT	REPORT OF	:
	*						
	\square		PLUG AND ABANDON	REMEDIAL WORK		Aire	RING CASING
PERFORM REMEDIAL WOR	* ├┤		PLUC AND ABANDON	'			—
TEMPORARILY ABANDON				COMMENCE DRILLING OP	N5.	PLUG	AND ABANDONMENT
PULL OR ALTER CASING			CHANGE PLANS	CASING TEST AND CEMEN	י ביס ביי		·
				Deepen Deepen	in San Ar	ndres	
OTHER							
		•					
17. Describe Proposed work) SEE RULE 1		Operations (Cle	early state all pertinent de	tails, and give pertinent a	lates, including	estimated date of	starting any proposes
1.	RIGGEL	UP. PU	JLL RODS AND I	PUMP. INSTALI	BOP. P	ILL TUBING	
	1. RIGGED UP. PULL RODS AND PUMP. INSTALL BOP. PULL TUBING. 2. DEEPEN TO 4736' (TOTAL DEPTH).						
		40 G 47 G	00'. ACIDIZE	OPEN-HOLE W/	10.000 6	ALS 15% N	JEFE
3.	SET PI	AR & 400	ACIDIAL	OF BOOK GATE	707000 C	4 MOMU P	NTT C
			GES USING 100	U# ROCK SALT	AND TOUG	# MOIN BE	TITIO
	BETWE	EN STAGE:	S.				
4.	IN STAL	L PUMPII	NG EQUIPMENT.	TEST AND RET	TURN TO 1	PRODUCTION	٧.
·							

		and belief	
18. I hereby	certily that the information above is true and c	omplete to the best of my knowledge and belief.	
#16HED	n.B. like	District Operations Mgr	DATE 10-23-94
APPROVED BY	Eddle W. Spark Olf & Geo Servic Servic	TITLE	OCT 29 1984
	OF APPROVAL, IF ANY:		