

Form 6-10
Revised 6-1-73

PERSONNEL	1	1
OFFICE	1	1
ADON	1	1

SUMMARY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG WELLS TO A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - "A" FORM C-101 FOR SUCH PROPOSALS.

 642
 07-06-0

TEXACO Inc.

Operator

P.O. Box 728, Hobbs, N.M. 88240

of well

of well _____ M _____ 660 _____ FEET FROM THE _____ South _____ LINE AND _____ 660 _____ FEET FROM
 _____ . _____ FEET FROM THE _____ LINE AND _____ FEET FROM
 West _____ 35 _____ TOWNSHIP _____ 17S _____ RANGE _____ 34E _____ RMPM
 LINE, SECTION _____

West _____ LINE. SECTION _____ TOWNSHIP _____ RANGE _____

15. Elevation (Show whether DF, RT, GR, etc.)
4027' DF

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF:

EMERGENCY WORK ☐
 LEAVE ABANDON ☐
 AFTER CASING ☐

Deepen in same zone

PLUG AND ABANDON ☐

CHANGE PLANS ☐

REMEDIAL WORK
COMMENCE DRILLING OPS.
CASING TEST AND CEMENT JOBS
OTHER _____

ALTERING CASING	☐
PLUG AND ABANDONMENT	☐
	☐

Deepen in same zone

by Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed
SEE RULE 1103. *Present TD is 4675'

*Present TD is 4675'

- 1. Deepen well 77' to TD of 4752'.
- 2. Spot 450 gallons 15% NEFE across open hole,
- 3. GIH w/treating packer and 8 joints tail pipe. Set packer at 4170'.
- 4. Load backside and acidize San Andres pay w/10,000 gallons 15% gelled NEFE and 10 gallons of scale inhibitor.
- 5. Flow/swab back any residue, release packer and POH.
- 6. Return to production.

W. B. Cade

District Operations Manual

6/28/85

55