Submit 3 Copies To Appr Office <u>District I</u> 1625 N. French Dr., Hobb <u>District II</u> 311 South First, Artesia, N <u>District III</u> 1000 Rio Brazos Rd., Azto		State of	f New Mexico		Form C-10	
1625 N. French Dr., Hobb District II 311 South First, Artesia, N District III		Ene , Minerals	and Natural Resources		Revised March 25, 19	
<u>District II</u> 311 South First, Artesia, N District III	s, NM 87240				NO. 30–025–02230	
District III	OIL CONSERVATION DIVISION				Type of Lease	
1000 Rio Brazos Rd Azte	rict III 2040 South Factored					
000 ICO DI 0200 ICO, I 000	ec, NM 87410	Santa	Fe, NM 87505		TE <b>X</b> FEE	
<u>District IV</u> 2040 South Pacheco, Sant	a Fe, NM 87505			6. State Oi B-1565	1 & Gas Lease No.	
SU		ES AND REPORTS	S ON WELLS	7. Lease N	ame or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:					Central Vacuum Unit	
	Gas Well	Other				
2. Name of Operator					8. Well No.	
hevron U.S.A. In	c			<u> </u>		
. Address of Operat	tor				me or Wildcat	
<u> 5 Smith Road - M</u>	idland, Texas	79705		Vacuum Gr	ayburg San Andres	
Well Location						
Unit Letter	:	660 feet from t	he <u>North</u> line a	nd660	feet from the <b>East</b> lin	
Section	36	Township		4E NMPM	County Lea	
		10. Elevation (Sho	w whether DR, RKB, RT,	GR, elC.)		
		<u> </u>	<u>3991' GR</u>	lation Donart or	- Other Data	
			Indicate Nature of N			
NOTI	CE OF INTE					
ERFORM REMEDIA	LWORK 🔲	PLUG AND ABAND	OON 🔲 REMEDIAL W	VORK	X ALTERING CASING	
		CHANGE PLANS		DRILLING OPNS.	PLUG AND ABANDONMENT	
ULL OR ALTER CAS	SING	MULTIPLE COMPLETION	CASING TES CEMENT JOB	T AND B		
				anin casing leak	/ Convert to flow	
<ol> <li>Describe Propos of starting any proposed or recompilation</li> </ol>	roposed work).	1 Operations (Clearly SEE RULE 1103. F	y state all pertinent details or Multiple Completions:	s, and give pertinent Attach wellbore di	t dates, including estimated date agram of proposed completion	
aa 40 00 NG	Ware and Whath	orford margarse 11	nit.			
03-19-02 MI	Key and Weath	erford reverse u scraper; pick up	2-3/8" prod that			
		and plug $w/2-3/8$	" mod that. Set plug	r@ 3910'; well :	still coming in flowing.	
03-25-02 Tri	ed to get plu	uq to test. No lu	ck. Came up one jt to	3850'. No luck	. Came up one jt to 3820'.	
No	luck. Reset p	okr @ 3820'; woul	d not hold pressure.			
03-26-02 <b>TOH</b>	flance mack	tbg, pkr and plu off, got CIBP se	t above tool. Open BC	OP; well came in	flowing, forcing CIBP out	
03-27-02 <b>Se</b> t	hole. Set CIE er. Shut down		up work string and pr		700'; circ 150 bbls brine	
of	empt to set p	pkr @ 3670' to te	st; no luck. Set pkr	@ 2025', lost 50	0 psi in 10 min. TIH w/pkr	
of wat 03-28-02 Att		,	have all and in La!	le		
of wat 03-28-02 Att and	1 work string.			LG.		
of wat 03-28-02 Att and	l work string. I w/pkr to 991	1'. Drop 2 100 IE	. Days of same in no.			
of wat 03-28-02 Att and 03-29-02 TOF	I w/pkr to 991					
of wat 03-28-02 Att and 03-29-02 TOF ereby certify that the i	I w/pkr to 991	is true and complete to	the best of my knowledge a	and belief.		
of wat 03-28-02 Att and 03-29-02 TOF ereby certify that the i	I w/pkr to 991	is true and complete to		and belief.		
of wat 03-28-02 Att and 03-29-02 TOF thereby certify that the i	H w/pkr to 991	is true and complete to	the best of my knowledge a	and belief.	Telephone No. 915-687-735	
of wat 03-28-02 Att and 03-29-02 TOF thereby certify that the i GNATURE wpe or print name L	H w/pkr to 991	is true and complete to	the best of my knowledge a	and belief.		
of wat 03-28-02 Att and 03-29-02 TOF nereby certify that the i	H w/pkr to 991	is true and complete to	TITLE Regulator	and belief.	Telephone No. 915-687-7359 AUG 1 9 200	