

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Bonos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-02236
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-155
7. Lease Name or Unit Agreement Name: Central Vacuum Unit
8. Well No. #66
9. Pool name or Wildcat Vacuum Grayburg- SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	
2. Name of Operator Texaco Exploration & Production, Inc.	
3. Address of Operator P. O. Box 3109, Midland, TX 79702	
4. Well Location Unit Letter H : 1980 feet from the North line and 660 feet from the East line Section 36 Township 17S Range 34E NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐	REMEDIAL WORK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐	CASING TEST AND CEMENT JOB ☐
OTHER: ☐	OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
- Record show attempted to spot cmt in O.H. Cmt 5 1/2" csg & tbq 4650'-2877' cut tbq @ 2345'
 - Perf 6 holes @ 2345' attempted to sqz unable spot 25 sx plug 2345'-2100' tag cmt @ 2112' (Yates-B-Salt)
 - Displace hole w/MLF 9.5# brine w/25# gel P/BBL
 - Perf 6 holes @ 1600', sqz 75 sx plug 1600'-1400' (T-Salt, 7 5/8" shoe) tag @ 1326'
 - Perf 6 holes @ 310' sqz 75 sx plug 310'-200' (10 3/4" shoe) tag @ 193'
 - Circ cmt 30' to surf w/15 sx - Install dry hole marker. 10/17/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER DATE 10/17/01
Type or print name Jimmy BAGLEY Telephone No. 915 683-4996
(This space for State use)
APPROVED BY [Signature] TITLE AdRep DATE 1-29-02
Conditions of approval, if any:

GW