

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-133
Revised 1-1-39

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02387
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Lease Name or Unit Agreement Name Lea ED State (NCT-A)
2. Name of Operator Chevron U.S.A. Inc.	8. Well No. 1
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Foot name or Wildcat Quail Ridge <i>Bore Springs</i>
4. Well Location Unit Letter <u>M</u> : <u>760</u> Feet From The <u>South</u> Line and <u>660</u> Feet From The <u>West</u> Line Section <u>16</u> Township <u>19S</u> Range <u>34E</u> NMNM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3777'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: add perfs. acidz. rtn to prod. ☒ ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

It is proposed to POH w/production equipment. Set RBP at 9700', tst to 500psi. Load hole w/ CKF and test csg to 500psi. Spot 250 gallons 15% NEFE HCL f/9510'-9354'. RIH w/ 4" csg gun loaded w/premium charges, 180 degree phasing and perf 9500' - 9510' @ 2 JHPF (20 holes), RIH w/ prod pkr, reverse excess acid into tbq. set pkr at 9400'. Acidize perfs 9500'-9510' w/1500 gallons 15% NEFE HCL. Swab back, Report results. ND WH, NU BOP, POH w/prod pkr. RIH w/ prod. equip. turn over to production dept.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry Sexton TITLE Tech. Asst. DATE 6-19-89

TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

JUN 21 1989