

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instruction
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. WELL TYPE ☐ OIL WELL ☐ GAS WELL ☐ OTHER	7. UNIT AGREEMENT NAME Mescalero Unit
2. NAME OF OPERATOR CARPER DRILLING COMPANY, INC.	8. FARM OR LEASE NAME Mescalero Unit Federal
3. ADDRESS OF OPERATOR Artesia, New Mexico	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1980' From South line 1980' From East line	10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T 19S, R 34E,
15. ELEVATIONS (Show whether DE, RT, GR, etc.) 3772' GR	12. COUNTY OR PARISH Lea
	13. STATE New Mexico

16 Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PBTD 4876'.**Perforated 4448'-4463' with 2 jets per foot. Acidized with 300 gallons, fractured with 500 barrels slick water with 24,000 lb. sand. After recovery of all load, well swabbed 100% formation water.****Set cast iron Bridge plug at 4200'. Perforated 3933'-3943' with 2 jets per foot. Acidized with 300 gallons, fractured with 460 bbls. water and 24,000 lbs. sand. After recovery of all load, well swabbed 100% formation water.****We propose to plug and abandon as follows:****Cut off 4 1/2" casing at 3000'.****Set 30 sacks cement from 4200' to 3840'.****Set 50 sacks cement from 1850'-1750' (Inside and outside 10 3/4" casing).****Set 20 sacks cement at surface with marker.****Heavy mud between cement plugs.****Verbal approval obtained from Mr. Arthur Brown, June 12, 1964.**

18. I hereby certify that the foregoing is true and correct

SIGNED

Vincent Foster

TITLE

Petroleum Engineer

DATE

June 15, 1964

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.