

APPROVED

Form 9-551a
(Feb. 1961)

JAN 19 1961

OFFICE COPY

Budget Bureau No. 48-2224
Approval expires 12-31-60.

(SUBMIT IN TRIPLICATE)

E. W. STANDLEY
DISTRICT ENGINEER

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico

Lease No. 086

Unit

JAN 4 1961

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)
D.G. Stevens & Chas. B. Gillespie, Jr. #1 Superior-Federal

December 5

1960

Well No. 1 is located 660 ft. from ^{NE} line and 1980 ft. from ^{SE} line of sec. 25
SW/4 Section 25 19 South 34 East N.M.P.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
West Pearl Queen Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3742 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Under verbal authority of James Knauf with U.S.G.S., Artesia, New Mexico, obtained November 17, 1960, this well was plugged and abandoned in the following manner:

1. Filled hole with heavy mud and set 15 sack cement plug from bottom hole plug at 4830 to 4658.
2. Shot off 4 1/2" casing at 3228' and set 20 sack cement plug in and out of casing from 3248' to 3148'. 1876' casing left in hole from 3228' to 5095'.
3. Set 20 sack cement plug at 1900' back to 1800'.
4. Set 25 sack plug at bottom of surface casing from 220' to 160'.
5. Set 5 sack cement plug at top of surface casing and placed regulation dry hole marker in cement.
6. Cleaned up location.

NOTED

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.
Company D.G. Stevens & Chas. B. Gillespie, Jr.

JAN 19 1961

Address 105 Dale Building

GORDON

Roswell, New Mexico

By

Title Agent

Inspected 1-7-61 OK for Abstract. JST