

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-02406
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-6005-1
7. Lease Name or Unit Agreement Name Lea K State
8. Well No. 1
9. Pool name or Wildcat <i>Pearl Queen + Pearl (Seven Rivers, South)</i>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3703 SCF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Xeric Oil & Gas Co.

3. Address of Operator
P.O. Box 51311 Midland, Tx. 79710

4. Well Location
Unit Letter L : 1980 Feet From The South Line and 660 Feet From The West Line
Section 36 Township 19-S Range 34E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3703 SCF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10/30/91 Spot 35 sx cmt on top of CIBP @ 4250'

10/30/91 Circ. hole w/105 BBLs. 10# brine w/1/2 sx salt gel per BBL.

10/30/91 Set 5 1/2 CIBP @ 3850 and cap w/35 sx cmt. (TOC @ 3500')

10/31/91 Perf @ 1850 and set 5 1/2 C.R. Sqz. w/200 sx class C cmt. Unstung and cap w/100 sx cmt. TOC @ 1050'

10/31/91 Spot 15 sx cmt from 30' to surface.

10/31/91 Cut off well head, weld on steel plate w/dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Louie French TITLE P&A Supervisor DATE 10/31/91

TYPE OR PRINT NAME Louie French TELEPHONE NO. 915 563-2805

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE NOV 09 1993

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

NOV 07 1991

OCD
HOBBS OFFICE