

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-5316
7. Unit Agreement Name
8. Farm or Lease Name State "V"
9. Well No. #1
10. Field and Pool, or Wildcat Wildcat
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-
2. Name of Operator Tom L. Ingram
3. Address of Operator P. O. Box 1757, Roswell, NM 88201
4. Location of Well UNIT LETTER H, 1787 FEET FROM THE North LINE AND 467 FEET FROM THE East LINE, SECTION 3 TOWNSHIP 17-S RANGE 35-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3969 DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER TA <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal approval obtained from NMOCC to P & A on December 12, 1977.

December 12, 1977, to December 22, 1977

Set cast iron bridge plug @ 9160'.
Put 10 sx cement on top of plug.
Cut 5½" csg @ 8112' with jet cutter.
Pulled 5½" csg. & set 35 sx plug in & out of 5½" stub. Top of plug @ 8042'.
Set 45 sx cement plug @ 7845'.
Set 45 Sx cement plug @ 6495'.
Set 70 sx cement plug @ 5000'.
Top plug @ 4830'.

Mud laden brine between all plugs.

Well temporarily abandoned and held for possible use as a salt water disposal well.

These operations were witnessed by the NMOCC.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Margaret P. Coelver TITLE CLERK DATE 1/3/78

APPROVED BY Orig. Signed By TITLE Jerry Sutton DATE JUL 25 1980

CONDITIONS OF APPROVAL, IF ANY:
Dist 1

Expired 1/3/80 (2nd)