

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. **30-025-02845**

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
B-2264-1

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
**EAST VACUUM GB/SA UNIT
TRACT 2155**

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No.
084

2. Name of Operator
Phillips Petroleum Company

9. Pool name or Wildcat
VACUUM GB/SA

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

4. Well Location
Unit Letter **J** : **1175** Feet From The **SOUTH** Line and **2500** Feet From The **EAST** Line
Section **21** Township **17 S** Range **35 E** NMPM **LEA** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3956.6' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- MIRU. NU BOP. SET 5-1/2" CIBP AT 4350'. CIRCULATE CSG W/9.5 MUD-LADEN FLUID.
- SPOT PLUG NO. 1 (35 SX CMT) 4350'-4130'. COVERS THE GB/SA.
- SPOT PLUG NO. 2 (25 SX CMT) 3000'-2900'. COVERS THE YATES.
- SPOT PLUG NO. 3 (25 SX CMT) 1768'-1668'. COVERS THE SALT TOP AND SURFACE SHOE.
- PERFORATE 5-1/2" CSG AT 400. PUMP PLUG NO. 4 (100 SX CMT) 400'-3'.
- CUT OFF CASING 3' BELOW GROUND LEVEL. INSTALL MONUMENT MARKER. PERFORM RECLAMATION WORK.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *L. M. Sanders* TITLE SUPERVISOR, REG. AFFAIRS DATE 3/3/95

TYPE OR PRINT NAME L. M. SANDERS TELEPHONE NO. 915/368-1488

(This space for State Use)

Orig. Signed by
Paul Kuntz
Geologist

APPROVED BY _____ TITLE _____ DATE **MAR 07 1995**

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAY 08 1995
JED HUBBS
OFFICE