

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-02845
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-2264-1
7. Lease Name or Unit Agreement Name	EAST VACUUM GB/SA UNIT TRACT 2155
8. Well No.	084
9. Pool name or Wildcat	VACUUM GRAYBURG/SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3956.6' GR	

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	4. Well Location Unit Letter J : 1175 Feet From The SOUTH Line and 2500 Feet From The EAST Line Section 21 Township 17 S Range 35 E NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3956.6' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: CLEANED OUT AND TA'D ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/08/94 MIRU DDU. COOH LD RODS AND PUMP. NU BOP AND PAN.  
12/09/94 COOH W/TBG. TRIP SAND PUMP. TAG @ 4740'. CATCH SAMPLE OF IRON SULFIDE.  
12/12/94 PU WORKSTRING TBG, TRIP BIT AND SCRAPER TO 4427'.  
12/13/94 GIH W/PKR AND TBG. SET PKR @4396'. SWABBED.  
12/14/94 SWABBED.  
12/15/94 SWABBED. RELEASE PKR COOH. GIH W/CIBP AND TBG TO 4392'.  
12/16/94 SET CIBP @4392'. CIRC. PKR FLUID. COOH LD TBG. LOAD AND TEST TO 500# FOR 30 MIN.  
OK. RDMO DDU. LEAVE WELL IN TA STATUS.

This Approval of Temporary  
Abandonment Expires 1-1-2000

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE SUPERVISOR, REG. AFFAIRS DATE 12/30/94  
TYPE OR PRINT NAME L. M. SANDERS TELEPHONE NO. 915/368-1488

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

JAN 31 1995

Legals

Sec 2155

SW SE Sec-21

T17-S R35E

Lea County

NM

Shelpley Co.

ELK MOUNTAIN CO

12/15

94